

Detailed Vehicle Specification

VIN	WF0HXXTTGHEJ17686				
Vehicle Line	T/TG	Market Derived Code	F		
Body Cab	T/KA	Ver. Series	T/GM		
Drive Type	T/D				
PLT CD	BX	TRS CD	T/AX	ENG CD	T/UH
Production Date	20-MAY-2014	Warranty Start Date	07-JAN-2016		
Selling Dealer	98060	Selling Country	ZAF		

GSAR Claim Key	Trx Code	Time In Service	Labor Hours	Dealership	DIST (Miles)	Repair Date	P
Details 15430515	5	20	0.2	LAZARUS FORD	42229	22-AUG-2017	*
	Customer Comments	CHILD LOCK CAMPAIGN					
	Tech Comments	CHECK CHILD LOCK ACTIVATION AND FIT GROMMET AND STICKER					
Details 15430312 *		20	1	LAZARUS FORD	42229	28-AUG-2017	B
	Customer Comments	TOWED IN - NO POWER					
	Tech Comments	F. TOWED IN: NO POWER & NON STARTING AT TIMES C. MAF SENSOR DAMAGED (CAMPAIGN SYSTEM , DPF BLOCKED - CANNOT RUN ENGINE TO DO REGENERATION R. REPLACE MAF S 15KM 16489KM 17/06/2016 30KM 31141KM 14/10/2016 45KM 44012KM 25/02/2017 60KM 60860K					
Details 15476474 1		20	0.4	LAZARUS FORD	42229	28-AUG-2017	*
	Customer Comments	NO POWER - CAMPAIGN NOT DONE BY PREVIOUS DEALER AS PER FMCSA CLAIM FILTER W					
	Tech Comments	TRANSIT AIR FILTER WATER INGRESS CERTAIN 2014 TO 2015 MODEL YEAR TRANSIT VEHICLE DECEMBER, 2013 THROUGH 27TH OCTOBER, 2014 ** AS PER FMCSA ADJUDICATOR - CLAIM RESULT OF CAMPAIGN, I COULD ONLY CLAIM THE SENSOR SEPARATELY (REFER V25182) *					
Details 16282896 *		24	1	LAZARUS FORD	47285	30-NOV-2017	B
	Customer Comments	LOSS OF POWER WHILE DRIVING					
	Tech Comments	F. VEHICLE IN LIMP MODE & ENGINE SYSTEM FAULT C. DPF PRESSURE TOO HIGH R. DIAGN COMPLETED PROCESS BUT DPF PRESSURE TOO HIGH ZIP FILE uploaded NO LABOUR OF 31441KM 14/10/2016 45KM 44012KM 25/02/2017 60KM 60860KM 24/06/2017 75KM 76098KM 27/					
Details 16894938 *		26	1	MCCARTHY FORD SILVER LAKES	48637	14-FEB-2018	B
	Customer Comments	(P) ATTEND TO ENGINE LIGHT ON					
	Tech Comments	(P) ATTEND TO ENGINE LIGHT ON (C) DPF FILTER HAS SOOT ACCUMULATION, REGENARATI 22/02/2018 09:00**					
Details 17277873 *		28	0.5	MCCARTHY FORD SILVER LAKES	51896	06-APR-2018	C
	Customer Comments	(P) NO POWER					
	Tech Comments	(P) NO POWER (C) BOTTOM BOOST PIPE BURST (R) REPALCE BOOST PIPE *PHOTOS ATTAC 17/06/2016 31141KM 14/10/2016 44012KM 25/02/2017 60860KM 24/06/2017 74928KM 10/11/2017 DUCT AIR*					