

WORKORDER INFORMATION

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	3946154	9BSF4X20003946 154	2019-11-05	10	10470014

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
128547	ALRODE	1 Garfield Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	FITTING AIR CONTROL VALVE
1	Part	2621183	Scania	CHECK VALV

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2021-02-23	15646	40304797

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2078001	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	JUMP START
1	Other	N/A	N/A	ATTEND TO BREAKDOWN AT RICHARDS BAY HARBOUR FOR NON START. DRIVER SAID VEHICLE STOOD FOR A OUPLE OF DAYS. JUMP STARTED THE VEHICLE. TESTED BATTERIES, FOUND OK.
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2021-06-02	18829	40307155

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2078977	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	18455104	MULTI	ASSEMBLY, ON ONE SIDE. SCANIA BUS
1	Other	N/A	N/A	REMOVE & FITTED NEW LHS MIRROR AS PER CUSTOMER REQUEST. MIRROR SUPPLIED BY CUSTOMER. TESTED, FOUND OK.
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2024-08-19	62713	40328996, 40329115

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2090422	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16005012	MULTI	TROUBLESHOOT ELECTRICAL CIRCUIT ON VEHICLE. INCL. USE MULTIM GENERAL
1	Labour	17155026	MULTI	O1 INCL. DETACH INSTRUMENT PANEL SECTION AND MOVE IT OUT OF
1	Labour	00005095	MULTI	Vehicle status, check before planned work.
1	Part	2627468	Scania	ECU ICL
1	Other	N/A	N/A	ATTEND TO CLUSTER NOT WORKING. FOUND INTERNAL FAULT. REMOVE & FITTED NEW CLUSTER. TESTED, FOUND OK.
1	Other	N/A	N/A	SUNDRY ITEMS
3	Labour	00256410	MULTI	Campaign *** RA/TC/RC
3	Part	1538087	Scania	VALVE
3	Part	1401693	Scania	UNION ASSY
3	Part	2058210	Scania	INSERT UNI
3	Part	2443492	Scania	PLASTIC PI
3	Part	0302612	Scania	NIPPLE
3	Other	N/A	N/A	CARRIED OUT TC - 231016 ASA cracks ZA F4x2 ABS5 CAMPAIGN
3	Other	N/A	N/A	CLAIM NO : 5168

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2022-08-23	34767	40316378

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2083446	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218731 =====
1	Labour	00215071	MULTI	S inspection according to the Scania inspection programme. F/K/N
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Labour	01005117	MULTI	TEST DRIVE VEHICLE.
2	Labour	01455010	MULTI	INCL. CLEANING AIR CLEANER AND OILING FILTER NECK. K/L/N
2	Part	1485592	Scania	AIR FILTER X36
2	Part	1760183	Scania	SAFETY ELE
2	Other	N/A	N/A	UPON INSPECTION CHECKED AND FOUND BOTH INNER AND OUTER AIR FILTERS BLOCKED AND VERY DIRTY. REMOVED AND REPLACED BOTH FILTERS. TESTED AND FOUND ALL OKAY.
3	Labour	00009000	MULTI	VEHICLE HEALTH CHECK

3	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE
3	Other	N/A	N/A	UPON INSPECTION CHECKED AND FOUND COOLANT CONCENTRATE IS BELOW SPEC. TOPPED UP 5L OF PURE GLYCOL. TESTED AND FOUND WITHIN SPEC ALL OKAY.
4	Labour	16255036	MULTI	RENEW BATTERIES, 2 OFF.
4	Part	2133962V	Local	VARTA BATTERY M18
4	Other	N/A	N/A	UPON INSPECTION CHECKED AND FOUND BATTERIES NOT HOLDING CHARGE, REMOVED AND REPLACED BOTH BATTERIES, TESTED AND FOUND ALL OKAY. REFERENCE 354361
4	Other	N/A	N/A	NEW SERIAL NO : C6C240292 0643 / C6C240292 0494
4	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-02-18	787	40299174, 40299263, 40299336, 40299303, 40299340, 40299338, 40299346, 40299341, 40299404, 40299387

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2074601	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	BYPASS APK SYSTEM
1	Part	0270317	Scania	PLUG
1	Part	0815362	Scania	STRAP
1	Other	N/A	N/A	CARRIED OUT BYPASS OF APK SYSTEM TEST DROVE, FOUND ALL OK.
1	Other	N/A	N/A	CLAIM NO: 203084
2	Subcontr	CASTING REPAIR SERVICES	N/A	FILL UP DIESEL
2	Other	N/A	N/A	FILLED UP WITH 128.17 LITRES DIESEL

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-08-24	9728	40301533

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2076228	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	01455010	MULTI	INCL. CLEANING AIR CLEANER AND OILING FILTER NECK. K/L/N
1	Part	1485592	Scania	AIR FILTER X36
1	Other	N/A	N/A	FOUND THE OUTER AIR FILTER BLOCKED DUE LOTS OF DUST WHERE THE VEHICLE IT OPERATES, CLEANED THE HOUSING AND REPLACED THE FILTER.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-04-15	2931	40299784

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2075037	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	10255095	MULTI	INCL. SUPPORT ON STANDS. GENERAL TIME FOR RENEWING PLASTIC P 1 OFF
2	Part	0812913	Scania	INS.SLEEVE
2	Other	N/A	N/A	ATTEND TO AIRLEAK UNDER DRIVER SEAT. REMOVED DRIVER SEAT FROM FLOOR. CHECKED AND FOUND 4MM PIPE LEAKING. FITTED NEW 4MM LINE CONNECTOR. FITTED BACK DRIVER SEAT. TESTED, FOUND OK.
2	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2021-01-27	14398	40304294, 40304295

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2077745	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16255029	MULTI	ONE OR BOTH BATTERIES. INCL. REMOVE AND FIT BATTERY COVER AN 140/180 AH
1	Other	N/A	N/A	ATTEND TO BREAKDOWN FOR NON START. CHECKED AND FOUND THAT BATTERY WATER TOO LOW. TOPPED UP WATER AND JUMP STARTED VEHICLE. WAITED A WHILE FOR BATTERIES TO CHARGE. FOUND BOTH BATTERIES NOT PICKING UPCHARGE. REPLACED BOTH BATTERIES. TESTED AND FOUND ALL GOOD. CHARGED REMOVED BATTERIES OVERNIGHT ON SLOW CHARGE. CARRIED OUT LOAD TEST AND FOUND VOLTAGE DROPPING TO 7.6 AND 8.1 V RESPECTIVELY .
1	Other	N/A	N/A	OLD SERIAL NO : 6200546785 00309384 / 9200640374 00401080 NEW SERIAL NO : C4C077251 1198 - C4C077252 0238
1	Other	N/A	N/A	DCP : 1748913F
1	Other	N/A	N/A	FRAS NO : DRFR789894
1	Other	N/A	N/A	CLAIM NO : 203492
2	Part	2133962V	Local	VARTA BATTERY M18
2	Other	N/A	N/A	ATTEND TO BREAKDOWN FOR NON START. CHECKED AND FOUND THAT BATTERY WATER TOO LOW. TOPPED UP WATER AND JUMP STARTED VEHICLE. WAITED A WHILE FOR BATTERIES TO CHARGE. FOUND BOTH BATTERIES NOT PICKING UPCHARGE. REPLACED BOTH BATTERIES. TESTED AND FOUND ALL GOOD. CHARGED REMOVED BATTERIES OVERNIGHT ON SLOW CHARGE. CARRIED OUT LOAD TEST AND FOUND VOLTAGE DROPPING TO 7.6 AND 8.1 V RESPECTIVELY .

2	Other	N/A	N/A	OLD SERIAL NO : 6200546785 00309384 / 9200640374 00401080 NEW SERIAL NO : C4C077251 1198 - C4C077252 0238
2	Other	N/A	N/A	OLD SERIAL NO : 6200546785 00309384 / 9200640374 00401080 NEW SERIAL NO : C4C077251 1198 - C4C077252 0238
2	Other	N/A	N/A	DCP : 1748913F
2	Other	N/A	N/A	FRAS NO : DRFR789894
2	Other	N/A	N/A	CLAIM NO : 203492
2	Other	N/A	N/A	FAILURE REPORT :

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-12-03	14349	40303570

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2077307	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	07015117	MULTI	ON ONE SIDE. INCL. SUPPORT ON STANDS, REMOVE AND FIT WHEEL DRUM BRAKE
1	Part	0132715	Scania	ANILHA DE AJUSTE
1	Part	0132714	Scania	ADJ WASHER
1	Part	1338019	Scania	O-RING PB
1	Part	0804782	Scania	RET RING PB
1	Other	N/A	N/A	ATTENDED TO VEHICLE WHICH FAILED COF FOR KING PIN PLAY. CHECKED AND FOUND THAT BOTH SIDE KINGS ARE OUT OF ADJUSTMENT .STRIPED OUT ALL COMPONENTS AND ADJUSTED KINGPINS USING SHIMS BOTH LHS AND RHS AS PER LMI AND ASSEMBLED ALL COMPONENTS .TESTED FOUND ALL OKAY.
1	Other	N/A	N/A	DCP : 0132715
1	Other	N/A	N/A	FRAS NO : DRFR775366
1	Other	N/A	N/A	CLAIM NO : 3409

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2022-05-18	32471	40314741

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2082563	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	17155026	MULTI	O1 INCL. DETACH INSTRUMENT PANEL SECTION AND MOVE IT OUT OF
1	Part	2627468	Scania	ECU ICL
1	Other	N/A	N/A	ATTEND TO ICL MALFUNCTION DISPLAYING ON DASH. CHECKED AND FOUND INSTRUMENT CLUSTER DEFECTIVE. REMOVE & FITTED NEW AND CARRIED OUT SPARE PARTS PROGRAMMING. TEST DRIVE VEHICLE, FOUND OK.
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-08-19	9728	40301525

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2076171	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215142	MULTI	SEE MAINTENANCE FORM FOR R MAINTENANCE. F 4X2
1	Other	N/A	N/A	CARRY OUR R-SERVICE AS PER INSPECTION SHEET
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2021-08-03	20924	40309193

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2079575	RICHARDS BAY	7 Brass Link Road	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218731 =====
1	Labour	00215071	MULTI	S inspection according to the Scania inspection programme. F/K/N
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Labour	16205143	MULTI	INCL. DETACH LAMP BRACKET AND ADJUSTMENT. HEADLAMP
2	Part	0246855	Scania	BULB H4
2	Other	N/A	N/A	UPON INSPECTION FOUND BOTH HEADLIGHT BULBS BLOWN. REMOVE HEADLIGHTS AND FITTED NEW BULBS. FITTED BACK THE HEADLIGHTS. TESTED, FOUND OK.
3	Labour	03305011	MULTI	INCL. ENLARGE RECESS FOR RETAINING STRAP, RUST-PROOF BRACKET LEFT OUTLET
3	Part	1863831	Scania	.V-CLAMP

3	Other	N/A	N/A	CHECKED AND FOUND V-CLAMP STRIPPED. REMOVE & FITTED NEW. TESTED, FOUND OK.
4	Labour	01455010	MULTI	INCL. CLEANING AIR CLEANER AND OILING FILTER NECK. K/L/N
4	Part	1760183	Scania	SAFETY ELE
4	Part	1485592	Scania	AIR FILTER X36
4	Other	N/A	N/A	CHECKED AND FOUND INNER AND OUTER AIR FILTERS GLOGGED. REMOVE & FITTED NEW, FOUND OK.
4	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3946154	NRB 70443	9BSF4X20003946 154	2020-01-27	100	11502229, 11502241

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2157	Central Support Centre	106 Adcock Ingram Street	ZA	Scania	F250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215220	MULTI	CARRIED OUT PDI
1	Labour	00008000	Local	CARRY OUT LOCAL BBM QA
1	Part	1714969	Scania	BBM QA
2	Labour	00215002	MULTI	INCL. BRAKE TESTING ON ROLLER BRAKE TESTER AND ELC CHECKING
3	Labour	16255037	MULTI	2 OFF, WITH HYDROMETER. INCL. OPEN AND CLOSE HATCH AND REMOV
4	Labour	16005003	MULTI	UPDATE SOFTWARE AND CLEAR FAULT CODES USING SCANIA DIAGNOSE
9	Labour	03055090	MULTI	INCL. ENGINE WASH, BLEED FUEL SYSTEM. PDE/HPI
9	Part	NYTUB05	Local	TUBING 12MM
9	Part	INSERT05	Local	INSERTO 12MM
9	Part	SLCON05	Local	M12 LINE CONNECTOR
9	Part	ARSUZC07	Local	ELBOWS 12MM
10	Part	ANO001	Local	SCANIA LOG DOMES 69X69
10	Labour	00008000	Local	FIT HUB STICKERS
11	Subcontr	IMTIMO LOGISTICS	N/A	DO COF AND DIESEL
11	Subcontr	BATELEUR TESTING STATION	N/A	DO COF
12	Subcontr	TRENTYRE	N/A	WHEEL ALIGNMENT
13	Subcontr	RELIABLE PETROLEUM	N/A	FILL R4000 DIESEL
14	Labour	00008000	Local	DO VALET

14	Other	N/A	N/A	SUNDRY ITEMS
----	-------	-----	-----	--------------