

FIN: ABJ 963424 60 516736

## Current advice for the vehicle:

none

















## Outstanding KDM:

none

## ESKULAB decisions:

none

## Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	21.02.2025		58	013056777	2-cylinder compressor Delivers oil into system	3531889	SA	00052	316262	km	1	000004226	04.03.2025
	21.02.2025		57	000261SV8	Travel expenses to breakdown location Service contract	3531889	SA	00052	316262	km	1	000004226	04.03.2025
	14.01.2025	AA	56	000318SV7	Telligent(R), maintenance system Service contract	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025	AB	55	013072048	Adapter, intake air, resonator Leaks	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025	AC	54	000311SV7	Maintenance work after (1) year (J1) Service contract	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025	AD	53	020000SV7	Replace coolant/antifreeze protection Service contract	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025	AE	52	000314SV7	Additional operation to 2nd WD Service contract	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025		51	042114D17	Brake lining, front Worn	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025		50	042214D17	Brake lining, rear Worn	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	14.01.2025		49	042273D17	Brake lining, leading axle/trailing axle Worn	3531199	SA	00052	311678	km	1	000004196	21.01.2025
	26.08.2024		48	05484M737	Combination switch, parking brake Electrical fault	3528833	SA	00052	289180	km	1	000004097	03.09.2024
	26.08.2024	AF	47	082123747	Light source, headlamp Contact fault/open circuit	3528833	SA	00052	289180	km	1	000004097	03.09.2024
	03.06.2024	AA	46	000318SV7	Telligent(R), maintenance system Service contract	3527784	SA	00052	267304	km	1	000004044	20.06.2024
	03.06.2024	AG	45	009102B28	Air filter element Clogged	3527784	SA	00052	267304	km	1	000004044	20.06.2024
	03.06.2024	AC	44	000311SV7	Maintenance work after (1) year (J1) Service contract	3527784	SA	00052	267304	km	1	000004044	20.06.2024
	03.06.2024		43	082141737	Light source, standing light Electrical fault	3527784	SA	00052	267304	km	1	000004044	20.06.2024

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	03.06.2024	AB	42	013072048	Adapter, intake air, resonator Leaks	3527784	SA	00052	267304	km	1	000004044	20.06.2024
	30.01.2024	AH	41	082137737	Light source, front fog lamp Electrical fault	3525623	SA	00052	240398	km	1	000003944	01.02.2024
	30.01.2024	AF	40	082123747	Light source, headlamp Contact fault/open circuit	3525623	SA	00052	240398	km	1	000003944	01.02.2024
	30.01.2024	AI	39	082023D17	Wiper blade, front Worn	3525623	SA	00052	240398	km	1	000003944	01.02.2024
	27.11.2023		38	00031DSV7	Maintenance, rear axle Service contract	3524717	SA	00052	225125	km	1	000003899	30.11.2023
	27.11.2023		37	080605737	Battery, transmitter key, infrared/radio remote control Electrical fault	3524717	SA	00052	225125	km	1	000003899	30.11.2023
	27.11.2023	AG	36	009102B27	Air filter element Clogged	3524717	SA	00052	225125	km	1	000003899	30.11.2023
	27.11.2023	AB	35	013072047	Adapter, intake air, resonator Leaks	3524717	SA	00052	225125	km	1	000003899	30.11.2023
	27.11.2023	AA	34	000318SV7	Telligent(R), maintenance system Service contract	3524717	SA	00052	225125	km	1	000003899	30.11.2023
	04.10.2023	AH	33	082137737	Light source, front fog lamp Electrical fault	3523657	SA	00052	212506	km	1	000003860	06.10.2023
	04.10.2023		32	000251SV7	Refill engine oil (outside maintenance) Service contract	3523657	SA	00052	212506	km	1	000003860	06.10.2023
	28.07.2023	AA	31	000318SV7	Telligent(R), maintenance system Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AB	30	013072047	Adapter, intake air, resonator Leaks	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023		29	00031ESV7	Maintenance, transmission Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AD	28	020000SV7	Replace coolant/antifreeze protection Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AJ	27	00030ESV8	Maintenance operations, once per year Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023		26	000317SV7	Adjust valve clearance Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AK	25	083108B27	Air/dust combination filter, heating and ventilation system Clogged	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AI	24	082023D17	Wiper blade, front Worn	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	28.07.2023	AE	23	000314SV7	Additional operation to 2nd WD Service contract	3522445	SA	00052	196533	km	1	000003813	02.08.2023
	11.04.2023	AA	22	000318SV7	Telligent(R), maintenance system Service contract	3520650	SA	00052	162521	km	1	000003736	15.04.2023
	11.04.2023	AI	21	082023D17	Wiper blade, front Worn	3520650	SA	00052	162521	km	1	000003736	15.04.2023
	11.04.2023	AG	20	009102B27	Air filter element Clogged	3520650	SA	00052	162521	km	1	000003736	15.04.2023
	11.04.2023	AB	19	013072047	Adapter, intake air, resonator Leaks	3520650	SA	00052	162521	km	1	000003736	15.04.2023
	11.04.2023		18	046538047	Intake line, power steering Leaks	3520650	SA	00052	162521	km	1	000003736	15.04.2023

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	03.04.2023		17	047011067	Tank cap, fuel tank Broken	3520559	SA	00052	160007	km	1	000003728	05.04.2023
	20.02.2023	AF	16	082123747	Light source, headlamp Contact fault/open circuit	3519702	SA	00052	140177	km	1	000003700	24.02.2023
	20.02.2023	AF	15	082123747	Light source, headlamp Contact fault/open circuit	3519702	SA	00052	140177	km	1	000003700	24.02.2023
	17.11.2022	AA	14	000318SV7	Telligent(R), maintenance system Service contract	3518269	SA	00052	119732	km	1	000003634	24.11.2022
	17.11.2022	AJ	13	00030ESV7	Maintenance operations, once per year Service contract	3518269	SA	00052	119732	km	1	000003634	24.11.2022
	17.11.2022	AB	12	013072047	Adapter, intake air, resonator Leaks	3518269	SA	00052	119732	km	1	000003634	24.11.2022
	17.11.2022	AD	11	020000SV7	Replace coolant/antifreeze protection Service contract	3518269	SA	00052	119732	km	1	000003634	24.11.2022
	17.11.2022	AK	10	083108B27	Air/dust combination filter, heating and ventilation system Clogged	3518269	SA	00052	119732	km	1	000003634	24.11.2022
	14.07.2022	AA	9	000318SV7	Telligent(R), maintenance system Service contract	3515774	SA	00052	85200	km	1	000003543	19.07.2022
	14.07.2022	AB	8	013072047	Adapter, intake air, resonator Leaks	3515774	SA	00052	85200	km	1	000003543	19.07.2022
	13.06.2022	AG	7	009102B27	Air filter element Clogged	3514964	SA	00052	70573	km	1	000003518	14.06.2022
	08.04.2022	AA	6	000318SV7	Telligent(R), maintenance system Service contract	3514138	SA	00052	48657	km	0	000000000	27.04.2022
	08.04.2022	AJ	5	00030ESV7	Maintenance operations, once per year Service contract	3514138	SA	00052	48657	km	0	000000000	27.04.2022
	08.04.2022	AB	4	013072047	Adapter, intake air, resonator Leaks	3514138	SA	00052	48657	km	0	000000000	27.04.2022
	08.04.2022	AK	3	083108B27	Air/dust combination filter, heating and ventilation system Clogged	3514138	SA	00052	48657	km	0	000000000	27.04.2022
	08.04.2022		2	082268737	Light source, turn signal light Electrical fault	3514138	SA	00052	48657	km	0	000000000	27.04.2022
	08.09.2021		1	000C17SV8	Commission, service contract, 5 Service contract	98596	SA	00196	750	km	0	000000000	23.09.2021