



Vehicle Information (Damage history)

01940

FIN: ABJ 963424 60 538211

Current advice for the vehicle:

none

Outstanding KDM:

none

ESKULAB decisions:

none

Damage history:

Typ	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	14.11.2024		100	005221D37	Tappet Worn out	3530796	SA	00052	421887	km	1	000004169	12.12.2024
	14.11.2024		99	025012D37	Vibration damper, clutch plate, single-plate dry clutch Worn out	3530796	SA	00052	421887	km	1	000004169	12.12.2024
	14.11.2024		98	024005077	Engine mount, front Torn/cracked	3530796	SA	00052	421887	km	1	000004169	12.12.2024
	08.08.2024	AA	97	000318SV7	Telligent(R), maintenance system Service contract	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024	AB	96	000311SV7	Maintenance work after (1) year (J1) Service contract	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		95	000314SV7	Additional operation to 2nd WD Service contract	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024	AC	94	009102B28	Air filter element Clogged	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024	AD	93	013072048	Adapter, intake air, resonator Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		92	046575047	Seal/sealing ring, mounting, power steering pump Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		91	08910F177	Transverse control arm bearing, tilting cab, rear Too much play	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		90	089115047	Vibration damper, rear, cab, tilting Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024	AE	89	082023D17	Wiper blade, front Worn	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		88	020240077	Poly-V-belt Torn/cracked	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		87	001424047	Gasket, end cover, camshaft/fuel pump, final drive, front Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		86	043753047	Magnetic threaded fitting, retarder Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	08.08.2024		85	001104047	Seal/sealing surface, oil pan, engine Leaks	3528633	SA	00052	407473	km	1	000004099	05.09.2024
	03.07.2024		84	080605737	Battery, transmitter key, infrared/radio remote control Electrical fault	3528020	SA	00052	400027	km	1	000004056	06.07.2024



Vehicle Information (Damage history)

01940

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	03.07.2024	AF	83	082141737	Light source, standing light Electrical fault	3528020	SA	00052	400027	km	1	000004056	06.07.2024
	18.06.2024		82	054011388	Wiring harness, starter battery Loose	3527792	SA	00052	393838	km	1	000004045	21.06.2024
	18.06.2024		81	000036ZZ8	Roadside assistance Special cost settlement	3527792	SA	00052	393838	km	1	000004045	21.06.2024
	23.05.2024	AG	80	082123747	Light source, headlamp Contact fault/open circuit	3527356	SA	00052	386978	km	1	000004025	24.05.2024
	23.05.2024	AF	79	082141737	Light source, standing light Electrical fault	3527356	SA	00052	386978	km	1	000004025	24.05.2024
	27.03.2024	AH	78	000261SV8	Travel expenses to breakdown location Service contract	ES50010	SA	00249	378889	km	1	000003990	05.04.2024
	27.03.2024		77	054001537	12 V battery Insufficient effect/power	ES50010	SA	00249	378889	km	1	000003990	05.04.2024
	28.02.2024		76	02000H047	Vent line, coolant, retarder Leaks	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AG	75	082123747	Light source, headlamp Contact fault/open circuit	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AF	74	082141737	Light source, standing light Electrical fault	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AA	73	000318SV7	Telligent(R), maintenance system Service contract	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AD	72	013072047	Adapter, intake air, resonator Leaks	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AI	71	000317SV7	Adjust valve clearance Service contract	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AB	70	000311SV7	Maintenance work after (1) year (J1) Service contract	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AE	69	082023D17	Wiper blade, front Worn	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	28.02.2024	AJ	68	042214D17	Brake lining, rear Worn	3526153	SA	00052	373608	km	1	000003970	08.03.2024
	13.01.2024	AK	67	021050P98	Trailer Towing Special expenditures for trucks	50318146	SA	00751	370178	km	1	000003971	09.03.2024
	13.01.2024	AL	66	000802SV8	Vehicle, tow Service contract	50318146	SA	00751	370178	km	3	000003971	09.03.2024
	13.01.2024	AH	65	000261SV8	Travel expenses to breakdown location Service contract	50318146	SA	00751	370178	km	3	000003971	09.03.2024
	13.01.2024	AM	64	013056777	2-cylinder compressor Delivers oil into system	50318146	SA	00751	370178	km	3	000003971	09.03.2024
	13.01.2024		63	121100ZZ7	Refurb COMP & EAPU parts warranty Special cost settlement	50318146A	SA	00751	370178	km	1	000003979	21.03.2024
	12.01.2024		62	043244047	Brake hose, compressed air Leaks	1569138	SA	00176	369658	km	1	000003951	10.02.2024
	12.01.2024	AH	61	000261SV8	Travel expenses to breakdown location Service contract	1569138	SA	00176	369658	km	1	000003951	10.02.2024
	30.11.2023	AC	60	009102B27	Air filter element Clogged	50317486	SA	00751	359700	km	1	000003921	30.12.2023
	30.11.2023	AN	59	042101077	Brake disc, front Torn/cracked	50317486	SA	00751	359700	km	1	000003921	30.12.2023
	30.11.2023	AO	58	042114D17	Brake lining, front Worn	50317486	SA	00751	359700	km	1	000003921	30.12.2023
	29.11.2023	AH	57	000261SV8	Travel expenses to breakdown location Service contract	50317232	SA	00751	359555	km	1	000003927	09.01.2024



Vehicle Information (Damage history)

01940

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	29.11.2023		56	039311047	Seal ring, wheel hub, forward-trailing/trailing axle Leaks	50317232	SA	00751	359555	km	2	000003927	09.01.2024
	03.10.2023	AA	55	000318SV7	Telligent(R), maintenance system Service contract	1567595	SA	00140	333300	km	1	000003868	18.10.2023
	03.10.2023	AC	54	009102B27	Air filter element Clogged	1567595	SA	00140	333300	km	1	000003868	18.10.2023
	03.10.2023	AD	53	013072047	Adapter, intake air, resonator Leaks	1567595	SA	00140	333300	km	1	000003868	18.10.2023
	03.10.2023		52	00031ESV7	Maintenance, transmission Service contract	1567595	SA	00140	333300	km	1	000003868	18.10.2023
	03.10.2023	AJ	51	042214D17	Brake lining, rear Worn	1567595	SA	00140	333300	km	1	000003868	18.10.2023
	29.07.2023	AH	50	000261SV8	Travel expenses to breakdown location Service contract	34723	SA	00097	303483	km	1	000003816	05.08.2023
	29.07.2023		49	020029047	Return line, coolant, compressor, compressed air system Leaks	34723	SA	00097	303483	km	2	000003816	05.08.2023
	27.07.2023		48	000251SV7	Refill engine oil (outside maintenance) Service contract	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	27.07.2023		47	01300B047	Seal, air compressor, crankcase Leaks	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	27.07.2023	AD	46	013072047	Adapter, intake air, resonator Leaks	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	27.07.2023		45	035021737	Temperature sensor, rear axle gear oil Electrical fault	52802395	SA	08200	303201	km	2	000003818	09.08.2023
	27.07.2023		44	046532047	High pressure line, Servolock Leaks	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	27.07.2023	AP	43	08221F737	Light source, taillamp Electrical fault	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	27.07.2023		42	082268737	Light source, turn signal light Electrical fault	52802395	SA	08200	303201	km	1	000003818	09.08.2023
	18.07.2023	AH	41	000261SV8	Travel expenses to breakdown location Service contract	50315664	SA	00751	300587	km	1	000003812	01.08.2023
	18.07.2023		40	054015388	Battery cable Loose	50315664	SA	00751	300587	km	1	000003812	01.08.2023
	08.05.2023	AA	39	000318SV7	Telligent(R), maintenance system Service contract	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023	AC	38	009102B27	Air filter element Clogged	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023	AD	37	013072047	Adapter, intake air, resonator Leaks	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023	AQ	36	00030ESV7	Maintenance operations, once per year Service contract	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023	AO	35	042114D17	Brake lining, front Worn	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023	AJ	34	042214D17	Brake lining, rear Worn	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023		33	042201077	Brake disc, rear Torn/cracked	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023		32	042211D67	Fixed caliper, rear Stiff/sluggish	52801579	SA	08200	268584	km	1	000003766	27.05.2023



Vehicle Information (Damage history)

01940

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	08.05.2023	AR	31	082137737	Light source, front fog lamp Electrical fault	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	08.05.2023		30	035513737	Indicator switch, differential lock, rear axle Electrical fault	52801579	SA	08200	268584	km	1	000003766	27.05.2023
	31.03.2023	AS	29	00031DSV7	Maintenance, rear axle Service contract	52801237	SA	08200	246776	km	1	000003739	20.04.2023
	15.02.2023	AT	28	042273D17	Brake lining, leading axle/trailing axle Worn	52800931	SA	08200	235011	km	1	000003717	21.03.2023
	15.02.2023	AS	27	00031DSV7	Maintenance, rear axle Service contract	52800931	SA	08200	235011	km	1	000003717	21.03.2023
	19.01.2023	AA	26	000318SV7	Telligent(R), maintenance system Service contract	115293	SA	08200	209993	km	1	000003691	11.02.2023
	19.01.2023	AS	25	00031DSV7	Maintenance, rear axle Service contract	115293	SA	08200	209993	km	1	000003691	11.02.2023
	19.01.2023	AM	24	013056777	2-cylinder compressor Delivers oil into system	52800475	SA	08200	209993	km	13	000003784	22.06.2023
	19.01.2023	AL	23	000802SV8	Vehicle, tow Service contract	52800475	SA	08200	209993	km	1	000003712	14.03.2023
	19.01.2023	AK	22	021050P98	Trailer Towing Special expenditures for trucks	52800475	SA	08200	209993	km	1	000003712	14.03.2023
	21.12.2022	AC	21	009102B27	Air filter element Clogged	52800286	SA	08200	191364	km	1	000003667	10.01.2023
	21.12.2022		20	020000SV7	Replace coolant/antifreeze protection Service contract	52800286	SA	08200	191364	km	1	000003667	10.01.2023
	05.10.2022	AA	19	000318SV7	Telligent(R), maintenance system Service contract	133796	SA	08178	161542	km	1	000003606	15.10.2022
	05.10.2022	AG	18	082123737	Light source, headlamp Electrical fault	133796	SA	08178	161542	km	1	000003606	15.10.2022
	05.10.2022	AR	17	082137737	Light source, front fog lamp Electrical fault	133796	SA	08178	161542	km	1	000003606	15.10.2022
	08.08.2022	AN	16	042101077	Brake disc, front Torn/cracked	125026	SA	08178	127352	km	1	000003563	16.08.2022
	07.07.2022	AQ	15	00030ESV7	Maintenance operations, once per year Service contract	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AI	14	000317SV8	Adjust valve clearance Service contract	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AA	13	000318SV7	Telligent(R), maintenance system Service contract	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AD	12	013072047	Adapter, intake air, resonator Leaks	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AO	11	042114D17	Brake lining, front Worn	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AJ	10	042214D17	Brake lining, rear Worn	120144	SA	08178	101766	km	2	000003546	22.07.2022
	07.07.2022	AT	9	042273D17	Brake lining, leading axle/trailing axle Worn	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022		8	047011D67	Tank cap, fuel tank Stiff/sluggish	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022	AP	7	08221F737	Light source, taillamp Electrical fault	120144	SA	08178	101766	km	1	000003546	22.07.2022
	07.07.2022		6	083108B27	Air/dust combination filter, heating and ventilation system Clogged	120144	SA	08178	101766	km	1	000003546	22.07.2022



Vehicle Information (Damage history)

01940

Type	Rep. Date	X	#	Damage code	Damage code description	Claim No.	L-KZ	Area	LL	M	E C	Credit note no.	Credit note date
	07.07.2022		5	083265077	Chafe protection, refrigerant hose Torn/cracked	120144	SA	08178	101766	km	1	000003546	22.07.2022
	21.04.2022		4	046922537	LSPADAPTER	163988	SA	08178	51579	km	0	000000000	06.05.2022
	21.04.2022	AI	3	000317SV8	Adjust valve clearance Service contract	63988	SA	08178	51579	km	0	000000000	29.04.2022
	21.04.2022	AA	2	000318SV7	Telligent(R), maintenance system Service contract	63988	SA	08178	51579	km	0	000000000	29.04.2022
	03.12.2021		1	000C17SV8	Commission, service contract, 5 Service contract	98955	SA	00196	750	km	0	000000000	26.05.2022