

## WORKORDER INFORMATION

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	3889544	9BSK4X20003889 544	2016-09-22	38	65284596

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
71289	EAST RAND	Cnr Sam Green & North Reef Rds	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00165015	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE
1	Labour	01005121	MULTI	TEST DRIVE VEHICLE.
1	Subcontr	MINTY'S SASOL NORTH REEF	N/A	FILL WITH DIESEL
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	3889544	9BSK4X20003889 544	2016-09-28	1419	20414270, 20414305

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2577672	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215221	MULTI	SEE THE FORM FOR PRE-DELIVERY INSPECTION. K
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Part	1771747	Local	CHASSIS GREASE (PO7453)
2	Labour	00215002	MULTI	INCL. BRAKE TESTING ON ROLLER BRAKE TESTER AND ELC CHECKING
3	Labour	00008000	Local	TOOK BUS FOR FILL UP
3	Subcontr	THE TRADING PAIR 120 CC	N/A	DIESEL
3	Subcontr	THE TRADING PAIR 120 CC	N/A	DIESEL
4	Subcontr	HEAVY DUTY ALIGNMENT CENTRE	N/A	W/A
5	Labour	00008000	Local	PROGRAM ECU PARAMETERS
5	Labour	03355061	MULTI	WITH SCANIA PROGRAMMER
6	Labour	00008000	Local	FIT WHEEL TRIMS
6	Part	1786571	Scania	HUB COVER
7	Labour	00008000	Local	TOOK BUS FOR COF
7	Subcontr	DEKRA AUTOMOTIVE (PTY)LTD	N/A	COF
8	Labour	09205040	MULTI	ON ONE RIM. REMOVE AND FIT TYRE ON RIM. EXCL. REMOVE AND FI DISC WHEEL
9	Labour	00008000	Local	FIT BATTERY HOLD DOWNS
10	Labour	00008000	Local	FIT WHEEL NUT CAPS
10	Part	1856639	Scania	-WHEEL NUT

11	Labour	00008000	Local	FIT HUB STICKERS
11	Part	ANO001	Local	SCANIA LOG DOMES 69X69
12	Labour	00008000	Local	REPAIR AIR LEAK AND SECURE HOSES
12	Part	SLCON03	Local	LINE CONNECTOR
12	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	3889544	9BSK4X20003889 544	2016-10-27	0	20414480

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2578336	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Part	2194290	Scania	BACKPACK
1	Part	2282558	Scania	BASEBALL CAP WHITE
1	Part	2410244	Scania	PEN
1	Part	2421709	Scania	KEY RING
1	Part	2190492	Scania	MUG
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	3889544	9BSK4X20003889 544	2016-10-28	1477	20414750

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2578373	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	FIT NUMBER PLATE HOLDERS
1	Part	VPN01	Local	NUMBER PLATE HOLDER
3	Part	2002314	Scania	BASEBALL C
3	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-04-20	6524	20419123

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2581861	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-04-26	7231	20419364

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2582006	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-06-05	8315	20420194

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2582776	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2017-06-08	8839	20420340

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2582861	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Operation 00215212, previously performed on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2022275	Scania	REP KIT
2	Other	N/A	N/A	The product 2022275, previously replaced on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793
2	Part	1771765	Local	SCANIA ENGINE OIL E7 15W-40
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Other	N/A	N/A	Operation 01205174, previously performed on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793
3	Part	1769799	Scania	O-RING
3	Other	N/A	N/A	The product 1769799, previously replaced on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793
3	Part	1769798	Scania	O-RING

3	Other	N/A	N/A	The product 1769798, previously replaced on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793
3	Part	2419091	Scania	SEALING WA
4	Subcontr	PAARL TRUCK ALIGNMENT SPECIALIST cc	N/A	PAARL
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES
5	Other	N/A	N/A	Operation 00215245, previously performed on 2017-04-11 at site S02, is related to work order 2581717. Previous mileage 6793

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-07-03	12078	20420935

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2583339	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	01015345	MULTI	ALL VALVES AND UNIT INJECTORS. INCL. USE MOBILE VEHICLE LIFT K DC9 PDE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-07-07	11050	20421180

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2583465	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACTOR

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-08-01	8839	20127182

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2584033	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	DEKRA AUTOMOTIVE (PTY)LTD	N/A	6 MONTHLY COF
1	Labour	00008000	Local	TAKE BUS FOR 6 MONTHLY COG

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-08-02	13466	20421823

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2584093	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2017-08-10	14935	20422008, 20422063

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2584239	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218732 =====
1	Labour	00215073	MULTI	M inspection according to the Scania inspection programme. K DC9, DC12, F DC9.
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2544995	Scania	FILTER
1	Part	2307617	Scania	DESIC CONT
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	1771765	Local	SCANIA ENGINE OIL E7 15W-40
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	The product 1771788, previously replaced on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
1	Other	N/A	N/A	=====
2	Labour	00256150	MULTI	APPLIES TO PRODUCTION CAMPAIGNS. RA/TC/RC
2	Part	2604635	Scania	MOUNTING K
2	Other	SCA	N/A	RA02-170201

3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
4	Part	1510905	Scania	AIR FILTER

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-09-06	15734	20422732

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2584833	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-10-04	17387	20423455

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2585444	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	CARRY OUT SAFETY CHECK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-10-10	17101	20423552

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2585581	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2017-11-09	20318	20424481

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2586283	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2022275	Scania	REP KIT
2	Other	N/A	N/A	The product 2022275, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
2	Part	1771765	Local	SCANIA ENGINE OIL E7 15W-40
2	Part	2419091	Scania	SEALING WA
2	Other	N/A	N/A	The product 2419091, previously replaced on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Other	N/A	N/A	Operation 01205174, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839

3	Part	1769799	Scania	O-RING
3	Other	N/A	N/A	The product 1769799, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
3	Part	1769800	Scania	O-RING
3	Other	N/A	N/A	The product 1769800, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES
5	Other	N/A	N/A	Operation 00215245, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-12-04	21534	20425015

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2586869	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2017-12-06	22556	20425148

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2586929	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Before vehicle at workshop: Predictive booking (X7) done: Yes/No (Date & time) Reservation /WO Quality checked: Yes/No (Date & time) Parts Quality checked: Yes/No (Date & time) Campaign check: Yes/No (Date & time) History checked: Yes/No (Date & time) VRS services offered to customer: Yes/No Remote diagnosis performed: Yes/No SUBC needed: Yes/No (Details) Previous offers: Yes/No (Details) Upselling: Yes/No (Details) Tools & equipment available: Yes/No (Details) GOP: Yes/No (Date & time) GOP Credit details: (Date & time) Credit limit details Customer contacted on X1: Yes Vehicle at workshop Vehicle at/in workshop: (Date & time) Quote done by: Foreman details (Date & time) Quote sent: Yes/No (Date & time) Delay or Incident: Yes/No Details: Free text

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-02-02	24110	20426464

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2588150	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-02-23	25345	20427003

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2588615	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2419091	Scania	SEALING WA
2	Other	N/A	N/A	The product 2419091, previously replaced on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
2	Part	2022275	Scania	REP KIT
2	Other	N/A	N/A	The product 2022275, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09

3	Other	N/A	N/A	Operation 01205174, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
3	Part	1769799	Scania	O-RING
3	Other	N/A	N/A	The product 1769799, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
3	Part	1769800	Scania	O-RING
3	Other	N/A	N/A	The product 1769800, previously replaced on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES
5	Other	N/A	N/A	Operation 00215245, previously performed on 2017/04/11 at site S02, is related to work order 2581717. Previous mileage 6793, on 2017/06/08 at site S02, is related to work order 2582861. Previous mileage 8839, on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-03-06	25268	20427300

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2588874	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2018-03-20	27059	20427613

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2589150	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Operation 00215201, previously performed on 2017/12/06 at site S02, is related to work order 2586929. Previous mileage 22556
1	Other	N/A	N/A	Before vehicle at workshop: Predictive booking (X7) done: Yes/No (Date & time) Reservation /WO Quality checked: Yes/No (Date & time) Parts Quality checked: Yes/No (Date & time) Campaign check: Yes/No (Date & time) History checked: Yes/No (Date & time) VRS services offered to customer: Yes/No Remote diagnosis performed: Yes/No SUBC needed: Yes/No (Details) Previous offers: Yes/No (Details) Upselling: Yes/No (Details) Tools & equipment available: Yes/No (Details) GOP: Yes/No (Date & time) GOP Credit details: (Date & time) Credit limit details Customer contacted on X1: Yes Vehicle at workshop Vehicle at/in workshop: (Date & time) Quote done by: Foreman details (Date & time) Quote sent: Yes/No (Date & time) Delay or Incident: Yes/No Details: Free text
2	Other	TRKM	N/A	TRAVELLING KILOMETERS
2	Labour	00008003	Local	TRAVELLING TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-04-12	28229	20428047

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2589595	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2018-05-10	30306	20428803

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2590141	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218733 =====
1	Labour	00215118	MULTI	L inspection according to the Scania inspection programme. F, PDE, DC9.
1	Labour	00215116	MULTI	L Inspection, - additional water separating filter. Additional water separating filter.
1	Labour	00215080	MULTI	Brake test on roller brake tester.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	1510905	Scania	AIR FILTER
1	Part	2562323	Scania	MAINTENANC
1	Part	0153468	Scania	STRAINER X 10
1	Part	1733658	Scania	FILTER ELE
1	Part	2002705	Scania	OIL FILTER
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Other	N/A	N/A	The product 2405798, previously replaced on 2018/02/23 at site S02, is related to work order 2588615. Previous mileage 25345
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	1771751	Local	BRAKE FLUID DOT 4
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.

1	Other	N/A	N/A	=====
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-05-10	20231	20428764

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2590142	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-06-14	33288	20429640

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2590912	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Operation 00215201, previously performed on 2017/12/06 at site S02, is related to work order 2586929. Previous mileage 22556, on 2018/03/20 at site S02, is related to work order 2589150. Previous mileage 27059
2	Labour	13015061	MULTI	U6 CONNECTOR UNDER STEERING WHEEL. INCL. REMOVE AND FIT SI WITHOUT AIRBAG.
2	Part	1856660	Scania	COIL SPRIN

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-07-10	35148	20430242

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2591478	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Operation 00215201, previously performed on 2017/12/06 at site S02, is related to work order 2586929. Previous mileage 22556, on 2018/03/20 at site S02, is related to work order 2589150. Previous mileage 27059, on 2018/06/14 at site S02, is related to work order 2590912. Previous mileage 33288

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-07-13	31940	20430339

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2591573	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-07-23	31940	20430588

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2591769	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-08-04	36534	20430789

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592007	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2018-08-29	38693	20431379

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592481	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008003	Local	TRAVELLING TIME
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09
1	Other	N/A	N/A	Operation 00215201, previously performed on 2017/12/06 at site S02, is related to work order 2586929. Previous mileage 22556, on 2018/03/20 at site S02, is related to work order 2589150. Previous mileage 27059, on 2018/06/14 at site S02, is related to work order 2590912. Previous mileage 33288, on 2018/07/10 at site S02, is related to work order 2591478. Previous mileage 35148

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-09-03	38428	20431472

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592564	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-09-10	39064	20431646

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592739	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Part	2547559	Scania	PRESSURE C
1	Other	N/A	N/A	REF MANUAL 40630

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-09-05	39465	20431696

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592651	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	02155028	MULTI	ON THE THERMOSTAT COVER MOUNTED ON THE ENGINE BLOCK. INCL. R DC09-DC13, OC09
1	Labour	02005031	MULTI	INCL. PRESSURE TEST RADIATOR CAP.
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Part	1755952	Scania	GASKET
1	Part	0816135	Scania	HOSE CLAMP

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2018-09-17	395712	20431820

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592898	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318, on 2018/02/23 at site S02, is related to work order 2588615. Previous mileage 25345
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2022275	Scania	REP KIT
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Other	N/A	N/A	Operation 01205174, previously performed on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318, on 2018/02/23 at site S02, is related to work order 2588615. Previous mileage 25345
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Subcontr	PAARL TRUCK ALIGNMENT SPECIALIST cc	N/A	WHEEL ALIGNMENT
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-09-20	39529	20431895

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2592975	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK
1	Other	N/A	N/A	NB: X INSPECTION DONE 14/12/2017

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-10-09	40591	20432290

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2593342	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBMCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-10-17	42138	20432574

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2593548	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2017/11/09 at site S02, is related to work order 2586283. Previous mileage 20318, on 2018/02/23 at site S02, is related to work order 2588615. Previous mileage 25345, on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-11-01	43078	20433025

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2593887	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-11-22	451321	20433608

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2594403	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218732 =====
1	Labour	00215073	MULTI	M inspection according to the Scania inspection programme. K DC9, DC12, F DC9.
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2562323	Scania	MAINTENANC
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Part	1510905	Scania	AIR FILTER
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
4	Labour	10015244	MULTI	ONE AXLE. INCL. SUPPORT ON STANDS, REMOVE AND FIT SINGLE OR DISC BRAKE
4	Part	2325212	Scania	BRAKE PAD
4	Part	2325213	Scania	BRAKE PAD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-12-04	45677	20433850

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2594662	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-12-11	46250	20434254

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2594831	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	TRACE AND REPAIR WIRES
1	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
1	Labour	16015027	MULTI	BEHIND GLOVE COMPARTMENT AT RELAY POSITION.
1	Part	0815362	Scania	STRAP
1	Part	1493046	Scania	RELAY

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2018-12-20	46253	20434366

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2595019	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	12055093	MULTI	RENEW TORQUE ROD, 2 OFF, REAR, INCL. USE MOBILE VEHICLE LIFT ADA1300
1	Part	1435944	Scania	REPAIR KIT

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-01-14	46253	20434686

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2595392	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-02-20	47535	20435556

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2596160	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2019-03-01	50229	20435844

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2596373	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/10/17 at site S02, is related to work order 2593548. Previous mileage 42138
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2022275	Scania	REP KIT
2	Part	1769800	Scania	O-RING
2	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-03-07	50045	20435925

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2596483	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-03-27	52338	20436459

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2596891	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215201	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13, OC09

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-04-03	52705	20436598

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2597030	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-04-26	54602	20437093

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2597462	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/10/17 at site S02, is related to work order 2593548. Previous mileage 42138, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2625884	Scania	REP KIT
2	Other	N/A	N/A	The product 2625884, previously replaced on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229
2	Part	2419091	Scania	SEALING WA
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Other	N/A	N/A	Operation 01205174, previously performed on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712
3	Part	1769799	Scania	O-RING

3	Other	N/A	N/A	The product 1769799, previously replaced on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229
3	Part	1769800	Scania	O-RING
3	Other	N/A	N/A	The product 1769800, previously replaced on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229
4	Labour	13005136	MULTI	TOE-IN AND STRAIGHT-AHEAD POSITION ON RIGID FRONT AXLE AND R 4X2 AM/AMA
5	Labour	10005044	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-05-03	54607	20437222

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2597576	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACTO WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-05-29	56931	20437770

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2598058	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Other	N/A	N/A	Operation 00215212, previously performed on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/10/17 at site S02, is related to work order 2593548. Previous mileage 42138, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229, on 2019/04/26 at site S02, is related to work order 2597462. Previous mileage 54602

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-06-19	56743	20438293

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2598485	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2019-06-27	58652	20438580

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2598691	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218733 =====
1	Labour	00215118	MULTI	L INSPECTION F, PDE, DC9.
1	Labour	00215116	MULTI	L INSPECTION, - ADDITIONAL WATER SEPARATING FILTER. ADDITIONAL WATER SEPARATING
1	Labour	00215230	MULTI	SEE THE L INSPECTION FORM. F/K/N AIR FILTER
1	Labour	00215185	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. ADDITIONAL WATER SEPARATING FUEL FILTER
1	Labour	00215193	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. AUTOMATIC GEARBOX
1	Labour	00215080	MULTI	L INSPECTION (BRAKE TEST)
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2562323	Scania	MAINTENANC
1	Part	0153468	Scania	STRAINER X 10
1	Part	2544995	Scania	FILTER
1	Part	1733658	Scania	FILTER ELE
1	Part	2002705	Scania	OIL FILTER
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	1771751	Local	BRAKE FLUID DOT 4
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE

1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Part	1510905	Scania	AIR FILTER
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-07-02	58763	20438673

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2598786	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-08-06	61002	20439520

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2599540	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-08-07	61930	20439587

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2599580	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2018/09/17 at site S02, is related to work order 2592898. Previous mileage 395712, on 2018/10/17 at site S02, is related to work order 2593548. Previous mileage 42138, on 2019/03/01 at site S02, is related to work order 2596373. Previous mileage 50229, on 2019/04/26 at site S02, is related to work order 2597462. Previous mileage 54602, on 2019/05/29 at site S02, is related to work order 2598058. Previous mileage 56931
2	Other	TRKM	N/A	TRAVELLING KILOMETERS
2	Labour	00008003	Local	TRAVELLING TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-09-13	64934	20440545

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2600372	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2153365	Scania	INSERT
2	Part	2625884	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
3	Part	2419091	Scania	SEALING WA
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-10-09	77569	20441202

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2600886	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
2	Labour	02105069	MULTI	AUTOMATIC K
2	Labour	02105073	MULTI	RENEW POLY-V-BELT, 1 OFF, IN ENGINE COOLING SYSTEM. K
2	Part	2197391	Scania	BELT TENSIONER
2	Part	1920231	Scania	POLY-V-BEL

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-10-11	67008	20441254

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2600934	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-10-18	67906	20441443

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2601113	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	02005031	MULTI	INCL. PRESSURE TEST RADIATOR CAP.
1	Labour	00008000	Local	PRESSURE VALVE ADJUST

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-10-21	67956	20441555

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2601168	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	02005031	MULTI	INCL. PRESSURE TEST RADIATOR CAP.
2	Labour	00008000	Local	RENEW HOSE CLAMPS AND FILL COOLANT
2	Part	1921956	Local	COOLANT PREMIX 50/50 20L

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-11-07	64391	20441996

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2601589	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-11-14	68989	20442173

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2601755	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2019-11-15	70325	20442254

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2601811	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2419091	Scania	SEALING WA
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2625884	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
4	Subcontr	PAARL TRUCK ALIGNMENT SPECIALIST cc	N/A	WHEEL ALIGNMENT
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2019-12-12	71775	20442996

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2602469	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2017-04-11	6793	20418966

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2581717	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13, OC09
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	1771765	Local	SCANIA ENGINE OIL E7 15W-40
2	Part	2022275	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES
6	Labour	16205134	MULTI	TWO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-02-04	71913	20444210

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2603513	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-06-03	83075	20456961

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2611980	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-10-26	114256	20470736

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2620370	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Other	N/A	N/A	NB: BUS NEED TO COME BACK FOR LEAKING AIR BELLOW

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-08-03	142285	20478003

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2625236	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-09-17	74933	20449377

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2607343	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-05-31	139584	20476268, 20476269, 20476270, 20476271

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2624074	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	0750226	Scania	O-RING
2	Part	1328242	Scania	O-RING
2	Part	1769799	Scania	O-RING
2	Part	1769800	Scania	O-RING
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	2153365	Scania	INSERT
3	Part	2625884	Scania	REP KIT
3	Part	2419091	Scania	SEALING WA
3	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AND REAR AXLES USING JOSAM 6X2, 6X2/2, 6X4, 6X6 JOSAM TRUCKALIGNER 2
5	Labour	10005032	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. 2 OR 3 AXLE VEHICLES
8	Labour	16005019	MULTI	General software update.

9	Labour	16005019	MULTI	General software update.
10	Labour	16005019	MULTI	General software update.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-12-01	88398	20461674

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2614831	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-05-05	105115	20465917

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617533	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-02-23	129143	20473703, 20473704, 20473705, 20473706

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2622425	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917
1	Part	2419091	Scania	SEALING WA
1	Part	2153365	Scania	INSERT
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2625884	Scania	REP KIT
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AND REAR AXLES USING JOSAM 6X2, 6X2/2, 6X4, 6X6 JOSAM TRUCKALIGNER 2
5	Labour	10005044	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. 2 OR 3 AXLE VEHICLES
6	Labour	00008000	Local	CARRY OUT BATTERY LMI

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-09-04	144746	20478736, 20478740

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2625780	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
---------	-----------	-------------	-----------	-------------

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-03-02	73734	20444892

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2604114	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-05-21	82501	20456677

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2611728	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	10015244	MULTI	ONE AXLE. INCL. SUPPORT ON STANDS, REMOVE AND FIT SINGLE OR DISC BRAKE
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Part	2325212	Scania	BRAKE PAD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-08-14	74918	20448422

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2606796	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-12-02	77652	20451822

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608820	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-01-13	126270	20472579

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2621678	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-07-14	74905	20447496

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2606221	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-03-01	129760	20473881

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2622537	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-11-24	123917	20471444, 20471445, 20471446, 20471447

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2620874	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Part	2419091	Scania	SEALING WA
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2625884	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AND REAR AXLES USING JOSAM 6X2, 6X2/2, 6X4, 6X6 JOSAM TRUCKALIGNER 2
5	Labour	10005044	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. 2 OR 3 AXLE VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-05-07	80866	20456165

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2611465	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-04-02	74901	20445576

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2604707	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCO POLO CARRIED OUT INSP

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-09-28	143826	20479389, 20479390, 20479391

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2626201	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218733 =====
1	Labour	00215180	MULTI	SEE FORM FOR L MAINTENANCE. K DC09-DC13
1	Labour	00215185	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. ADDITIONAL WATER SEPARATING FUEL FILTER
1	Labour	00215230	MULTI	SEE THE L INSPECTION FORM. F/K/N AIR FILTER
1	Labour	00215189	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. K/N
1	Labour	00215048	MULTI	SCANIA RETARDER CHANGE OIL AND RENEW FILTER K
1	Labour	00215230	MULTI	SEE THE L INSPECTION FORM. F/K/N AIR FILTER
1	Labour	00215193	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. AUTOMATIC GEARBOX
1	Labour	00215080	MULTI	L INSPECTION (BRAKE TEST)
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	1510905	Scania	AIR FILTER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1733658	Scania	FILTER ELE
1	Part	2544995	Scania	FILTER
1	Part	2562323	Scania	MAINTENANC
1	Part	2002705	Scania	OIL FILTER

1	Part	2001228	Scania	SEALING WA
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	1771740B	Local	ECOFLUID ZF GEARBOX OIL
1	Part	1771751	Local	BRAKE FLUID DOT 4
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	===== =====
2	Labour	01455019	MULTI	INCL. CLEAN AIR CLEANER, OIL FILTER NECK AND CLEAR FAULT COD K/N
2	Part	2734215	Scania	SAFETY CAR
3	Labour	13005103	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE, REAR AXLE AND STEERE 6X2/4, 6X2*4
8	Labour	02005032	MULTI	INCL. CHECK AND ADJUST ANTIFREEZE AND CORROSION PROTECTION. F/K/L
8	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE
9	Labour	13015092	MULTI	ONE OF THREE FOR RADIO OR CRUISE CONTROL. INCL. REMOVE AND F
9	Part	1870910	Scania	SWITCH

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-04-01	78966	20455199, 20455200, 20455201, 20455202

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2610841	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2625884	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-05-03	136298	20475492

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2623582	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-02-02	94347	20463425

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2615882	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-11-14	152358	20480442

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2627031	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-02-24	97201	20464049, 20464050

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2616277	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-05-19	106779	20466266

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617751	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-10-07	119395	20470063, 20470064, 20470065

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2620024	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218733 =====
1	Labour	00215180	MULTI	SEE FORM FOR L MAINTENANCE. K DC09-DC13
1	Labour	00215185	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. ADDITIONAL WATER SEPARATING FUEL FILTER
1	Labour	00215230	MULTI	SEE THE L INSPECTION FORM. F/K/N AIR FILTER
1	Labour	00215189	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. K/N
1	Labour	00215048	MULTI	SCANIA RETARDER CHANGE OIL AND RENEW FILTER K
1	Labour	00215080	MULTI	L INSPECTION (BRAKE TEST)
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	1510905	Scania	AIR FILTER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1733658	Scania	FILTER ELE
1	Part	2562323	Scania	MAINTENANC
1	Part	2002705	Scania	OIL FILTER
1	Part	2001228	Scania	SEALING WA
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140

1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Labour	01455019	MULTI	INCL. CLEAN AIR CLEANER, OIL FILTER NECK AND CLEAR FAULT COD K/N
2	Part	2734215	Scania	SAFETY CAR
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AND REAR AXLES USING JOSAM 6X2, 6X2/2, 6X4, 6X6 JOSAM TRUCKALIGNER 2
6	Labour	00265139	MULTI	SOFTWARE UPDATE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-05-16	106498	20466229, 20466230

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617711	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
2	Labour	10255094	MULTI	BETWEEN AIR COMPRESSOR AND CHASSIS. INCL. USE VEHICLE LIFTS, 1 OFF. K
2	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
2	Part	1887062	Scania	HOSE ASSY
2	Part	0815363	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-05-14	74901	20446273, 20447083, 20446985

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2605194	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16255063	MULTI	JUMP START AND CHECK THE BATTERIES.
1	Labour	16255026	MULTI	2 OFF, WITH HYDROMETER. INCL. REMOVE AND FIT BATTERY COVER.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-12-04	77730	20451912

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608872	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-03-10	78219	20454539

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2610452	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2024-06-03	161593	20485441

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2630478	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16005012	MULTI	TROUBLESHOOT ELECTRICAL CIRCUIT ON VEHICLE. INCL. USE MULTIM GENERAL
1	Labour	03265096	MULTI	RENEW NOX SENSOR, 1 OFF, ON CATALYTIC CONVERTER.
1	Labour	16005001	MULTI	DELETE FAULT CODES USING SCANIA DIAGNOS. SCANIA DIAGNOS
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
1	Part	2296799	Scania	NOX SENSOR
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-10-21	75607	20450623, 20450624

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608039	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
2	Labour	02305014	MULTI	FIRST. INCL. DRAIN AND FILL COOLANT. 1 OFF, FIRST.
2	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
2	Part	1886594	Scania	SEAL
2	Part	1857301	Scania	HOSE
2	Part	0816135	Scania	HOSE CLAMP
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX
2	Part	1916151	Scania	HOSE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-08-25	114612	20468937, 20468938

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619323	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2625884	Scania	REP KIT
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2419091	Scania	SEALING WA
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2023-09-14	146875	20479079

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2626001	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917, on 2023-02-23 at site S02, is related to work order 2622425. Previous mileage 129143, on 2023-04-13 at site S02, is related to work order 2623254. Previous mileage 134810, on 2023-05-03 at site S02, is related to work order 2623605. Previous mileage 136447, on 2023-05-31 at site S02, is related to work order 2624074. Previous mileage 139584, on 2023-08-03 at site S02, is related to work order 2625236. Previous mileage 142285, on 2023-08-18 at site S02, is related to work order 2625457. Previous mileage 143829
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-05-03	136447	20475566

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2623605	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917, on 2023-02-23 at site S02, is related to work order 2622425. Previous mileage 129143, on 2023-04-13 at site S02, is related to work order 2623254. Previous mileage 134810
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-05-24	107075	20466418

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617826	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	10015244	MULTI	ONE AXLE. INCL. SUPPORT ON STANDS, REMOVE AND FIT SINGLE OR DISC BRAKE
1	Labour	10005032	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER.
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Part	2325213	Scania	BRAKE PAD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-03-10	98618	20464391, 20464392, 20464393, 20464394

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2616552	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2625884	Scania	REP KIT
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
3	Part	2153365	Scania	INSERT
3	Part	2419091	Scania	SEALING WA
3	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-10-01	75005	20449745, 20449746

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2607541	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
2	Labour	16255029	MULTI	ONE OR BOTH BATTERIES. INCL. REMOVE AND FIT BATTERY COVER AN 140/180 AH
2	Part	2133962V	Local	VARTA BATTERY M18
3	Other	TRKM	N/A	TRAVELLING KILOMETERS
3	Labour	00008003	Local	TRAVELLING TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-04-07	102115	20465269

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617053	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-08-18	143829	20478286

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2625457	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Part	2419091	Scania	SEALING WA
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2153365	Scania	INSERT
2	Part	0750226	Scania	O-RING
2	Part	1328242	Scania	O-RING
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
3	Part	2625884	Scania	REP KIT
4	Labour	13005103	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE, REAR AXLE AND STEERE 6X2/4, 6X2*4
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-11-03	75007	20450885

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608257	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-09-14	117090	20469446

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619618	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-02-13	128330	20473376

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2622197	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-06-14	109249	20467071, 20467072, 20467073, 20467074

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2618207	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2625884	Scania	REP KIT
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2419091	Scania	SEALING WA
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES
7	Labour	00265139	MULTI	SOFTWARE UPDATE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-10-03	118635	20469928

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619950	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-09-01	115310	20469113

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619432	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-01-28	94214	20463280, 20463281, 20463282, 20463283

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2615771	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	2625884	Scania	REP KIT
2	Part	2419091	Scania	SEALING WA
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
4	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-09-28	75007	20449641

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2607490	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13
1	Other	N/A	N/A	Operation 00215212, previously performed on 2019/10/09 at site S02, is related to work order 2600886. Previous mileage 77569, on 2019/11/15 at site S02, is related to work order 2601811. Previous mileage 70325

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-07-06	109951	20467588

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2618539	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-11-17	153764	20480599, 20480600, 20480601

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2627112	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	XO MAINTENANCE. ACCORDING TO THE SCANIA MAINTENANCE PROGRAMM K DC09-DC13
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917, on 2023-02-23 at site S02, is related to work order 2622425. Previous mileage 129143, on 2023-04-13 at site S02, is related to work order 2623254. Previous mileage 134810, on 2023-05-03 at site S02, is related to work order 2623605. Previous mileage 136447, on 2023-05-31 at site S02, is related to work order 2624074. Previous mileage 139584, on 2023-08-03 at site S02, is related to work order 2625236. Previous mileage 142285, on 2023-08-18 at site S02, is related to work order 2625457. Previous mileage 143829, on 2023-09-14 at site S02, is related to work order 2626001. Previous mileage 146875, on 2023-09-28 at site S02, is related to work order 2626201. Previous mileage 143826, on 2023-11-01 at site S02, is related to work order 2626797. Previous mileage 152474
1	Part	2153365	Scania	INSERT
1	Part	0750226	Scania	O-RING
1	Part	1328242	Scania	O-RING
1	Part	2419091	Scania	SEALING WA
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE

2	Labour	01205140	MULTI	CHANGE ENGINE OIL. INCL. RENEW OIL FILTER, CLEAN CENTRIFUGAL
2	Part	2625884	Scania	REP KIT
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	01205174	MULTI	REMOVE AND FIT CENTRIFUGAL OIL CLEANER, 1 OFF. IN THE ENGINE DC09-DC13, OC09
3	Part	1769799	Scania	O-RING
3	Part	1769800	Scania	O-RING
4	Labour	13005103	MULTI	MEASURE WHEEL GEOMETRY USING COMPUTER-AIDED LASER. ALL WHEEL 6X2/4, 6X2*4
5	Labour	10005032	MULTI	ROLLER BRAKE TEST BRAKES. 2 OR 3 AXLE VEHICLES
7	Labour	02005019	MULTI	CHANGE COOLANT IN ENGINE COOLING SYSTEM. WITH SCANIA RETARDER.
7	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-11-01	152474	20480204

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2626797	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	X MAINTENANCE. ACCORDING TO THE SCANIA MAINTENANCE PROGRAMM K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917, on 2023-02-23 at site S02, is related to work order 2622425. Previous mileage 129143, on 2023-04-13 at site S02, is related to work order 2623254. Previous mileage 134810, on 2023-05-03 at site S02, is related to work order 2623605. Previous mileage 136447, on 2023-05-31 at site S02, is related to work order 2624074. Previous mileage 139584, on 2023-08-03 at site S02, is related to work order 2625236. Previous mileage 142285, on 2023-08-18 at site S02, is related to work order 2625457. Previous mileage 143829, on 2023-09-14 at site S02, is related to work order 2626001. Previous mileage 146875, on 2023-09-28 at site S02, is related to work order 2626201. Previous mileage 143826
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-11-14	122701	20471057

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2620643	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-03-16	74853	20445298

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2604396	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
2	Labour	12155046	MULTI	INCL. USE VEHICLE LIFTS. ELC
2	Labour	12155048	MULTI	CALIBRATE LEVEL SENSOR, 1 OFF, FOR AIR SUSPENSION. ELC
2	Part	1889797	Scania	LEVEL SENS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-09-04	144746	20478745

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2625790	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-07-14	84850	20458020

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2612617	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-08-02	142077	20477941

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2625209	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-11-05	76275	20450934

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608329	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-06-09	107743	20466836

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2618107	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-08-25	87190	20459098

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2613281	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-03-02	97560	20464157

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2616384	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-07-06	140785	20477254

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2624705	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-10-05	149756	20479496

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2626328	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-01-15	71913	20443682

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2603025	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-05-06	79524	20456134

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2611435	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-04-03	133797	20474739

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2623088	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-02-01	93050	20463369

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2615826	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2024-03-07	157627	20483286

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2628936	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	X MAINTENANCE. ACCORDING TO THE SCANIA MAINTENANCE PROGRAMM K DC09-DC13
1	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-11-23	77438	20451623, 20451624

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608650	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
2	Labour	00005004	MULTI	IMPLEMENT MANUAL DIAGNOSIS.
2	Labour	00008000	Local	TIGHTEN CLAMP
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-11-20	77437	20451513, 20451514

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2608627	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	02005031	MULTI	INCL. PRESSURE TEST RADIATOR CAP.
2	Labour	02305020	MULTI	FIRST. INCL. DRAIN AND FILL COOLANT. 1 OFF, FIRST.
2	Part	2773280	Scania	HOSE
2	Part	1422981	Scania	UNION
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-02-02	77917	20453471

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2609835	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT BODY INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-08-03	112146	20468356, 20468357

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2618969	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	00008000	Local	REPAIR AIR LEAK
2	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
2	Part	0815362	Scania	STRAP
2	Part	0815363	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-08-17	86739	20458889

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2613167	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-01-12	77731	20452802

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2609420	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-06-01	139599	20476320

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2624113	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-06-03	74901	20446445

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2605487	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO CARRIED OUT INSP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-04-14	134810	20475003, 20475004, 20475005, 20475006, 20475007, 20475008

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2623254	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215173	MULTI	SEE MAINTENANCE FORM FOR M MAINTENANCE. ADDITIONAL WATER SEPARATING FUEL FILTER
1	Labour	00215174	MULTI	SEE MAINTENANCE FORM FOR M MAINTENANCE. SCR
1	Labour	01208001	Local	RENEW ENGINE OIL CHANGE OIL FILTER CLEAN CENTRIFUGAL
1	Labour	03055004	MULTI	INCL. BLEED FUEL SYSTEM. EXCL. CLEAR FAULT CODES WITH SCANIA DC9-DC16
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Other	N/A	N/A	Operation 00005095, previously performed on 2022-11-24 at site S02, is related to work order 2620874. Previous mileage 123917, on 2023-02-23 at site S02, is related to work order 2622425. Previous mileage 129143
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Labour	00215273	MULTI	FIRE EXTINGUISHING SYSTEM. YEARLY MAINTENANCE ACCORDING TO T FIRE EXTINGUISHING SYSTEM ANNUAL SERVICE
1	Labour	00215161	MULTI	SEE FORM FOR M MAINTENANCE. K DC09-DC13
1	Part	2544995	Scania	FILTER
1	Part	2153365	Scania	INSERT
1	Part	0750226	Scania	O-RING
1	Part	1328242	Scania	O-RING

1	Part	1769799	Scania	O-RING
1	Part	1769800	Scania	O-RING
1	Part	1852189	Scania	PREFILTER
1	Part	1393640	Scania	FILTER WATER SEPARATOR
1	Part	1873018	Scania	FUEL FILTER X 12
1	Part	2625884	Scania	REP KIT
1	Part	2419091	Scania	SEALING WA
1	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Labour	01455019	MULTI	INCL. CLEAN AIR CLEANER, OIL FILTER NECK AND CLEAR FAULT COD K/N
2	Part	1510905	Scania	AIR FILTER
2	Part	2734215	Scania	SAFETY CAR
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AND REAR AXLES USING JOSAM 6X2, 6X2/2, 6X4, 6X6 JOSAM TRUCKALIGNER 2
4	Labour	10005032	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. 2 OR 3 AXLE VEHICLES
8	Labour	02005032	MULTI	INCL. CHECK AND ADJUST ANTIFREEZE AND CORROSION PROTECTION. F/K/L
8	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE
9	Labour	12055080	MULTI	INCL. SUPPORTING ON STANDS, REMOVING AND FITTING WHEEL, ADJU 1 OFF, FIRST BELLOWS ON ONE SIDE. ADA/ASA
9	Part	1726241	Scania	AIR SPRING

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-09-26	118042	20469827, 20469828, 20469829

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619811	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	16055044	MULTI	THE LOWER ALTERNATOR OR BOTH ALTERNATORS. INCL. REMOVE AND F K 1-2 OFF 150 A
2	Part	0570887	Scania	ALTERNATOR
3	Labour	02105055	MULTI	FIRST SELECT STANDARD TIME FOR RENEWING THE POLY-V-BELT, THE 1 OFF. DC9-DC16
3	Labour	02105122	MULTI	FIRST SELECT STANDARD TIME FOR RENEWING THE POLY-V-BELT, THE 1 OFF. DC09-DC16
3	Part	2129402	Scania	IDLER ROLL
3	Part	2863219	Scania	BELT TENSI

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-05-19	82237	20456523

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2611676	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-12-17	91754	20462167

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2615125	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2024-05-23	161031	20485180

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2630316	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	16005012	MULTI	TROUBLESHOOT ELECTRICAL CIRCUIT ON VEHICLE. INCL. USE MULTIM GENERAL
2	Labour	00008000	Local	REMOVE, CLEAN AND REFIT NOZZLES
2	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
2	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-02-03	127686	20473173

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2622038	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2023-03-22	132428	20474447

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2622871	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2020-05-07	74901	20445978

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2605078	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-11-24	91354	20461447

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2614693	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR X MAINTENANCE. K DC09-DC13

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2020-03-18	78853	20445297

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2604454	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218732 =====
1	Labour	00215073	MULTI	M inspection according to the Scania inspection programme. K DC9, DC12, F DC9.
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Labour	01208001	Local	RENEW ENGINE OIL CHANGE OIL FILTER CLEAN CENTRIFUGAL
1	Labour	03055004	MULTI	INCL. BLEED FUEL SYSTEM. EXCL. CLEAR FAULT CODES WITH SCANIA DC9-DC16
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Part	1510905	Scania	AIR FILTER
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-12-07	123468	20471769

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2621128	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-06-29	84424	20457679, 20457680, 20457681, 20457682

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2612386	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00215212	MULTI	SEE MAINTENANCE FORM FOR XO MAINTENANCE. K DC09-DC13
2	Labour	01205140	MULTI	(GENERAL REPAIR AREA) INCL. USE MOBILE VEHICLE LIFTS, REMOVE
2	Part	2625884	Scania	REP KIT
2	Part	2419091	Scania	SEALING WA
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	01205174	MULTI	INCL. USE MOBILE VEHICLE LIFTS, REMOVE AND FIT NOISE SHIELDS DC09-DC13, OC09
3	Part	1769800	Scania	O-RING
3	Part	1769799	Scania	O-RING
4	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
5	Labour	00215245	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. INCL. CHECK FOR LEAKS. TWO AXLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-12-02	88918	20461719

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2614868	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889544	2022-04-29	104817	20465763, 20465764, 20465765, 20465766

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617424	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218732 =====
1	Labour	00215073	MULTI	M inspection according to the Scania inspection programme. K DC9, DC12, F DC9.
1	Labour	00215114	MULTI	Renew water separating fuel filter, 1 off. Additional water separating filter.
1	Labour	01208001	Local	RENEW ENGINE OIL CHANGE OIL FILTER CLEAN CENTRIFUGAL
1	Labour	03055004	MULTI	INCL. BLEED FUEL SYSTEM. EXCL. CLEAR FAULT CODES WITH SCANIA DC9-DC16
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Other	N/A	N/A	=====
2	Labour	01455019	MULTI	INCL. CLEAN AIR CLEANER, OIL FILTER NECK AND CLEAR FAULT COD K/N

2	Part	1510905	Scania	AIR FILTER
2	Part	2734215	Scania	SAFETY CAR
3	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6
4	Labour	10005032	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2024-03-25	158810	20483946

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2629223	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
2	Labour	00215212	MULTI	XO MAINTENANCE. ACCORDING TO THE SCANIA MAINTENANCE PROGRAMM K DC09-DC13
2	Labour	00005095	MULTI	VEHICLE STATUS, CHECK BEFORE PLANNED WORK.
2	Part	2153365	Scania	INSERT
2	Part	0750226	Scania	O-RING
2	Part	1328242	Scania	O-RING
2	Part	1769799	Scania	O-RING
2	Part	1769800	Scania	O-RING
2	Part	1771789	Local	RENOLIT LUBRENE LX/CA 700 NEW CHASSIS GREASE
3	Labour	01205140	MULTI	CHANGE ENGINE OIL. INCL. RENEW OIL FILTER, CLEAN CENTRIFUGAL
3	Part	2625884	Scania	REP KIT
3	Part	2419091	Scania	SEALING WA
3	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
4	Labour	01205174	MULTI	REMOVE AND FIT CENTRIFUGAL OIL CLEANER, 1 OFF. IN THE ENGINE DC09-DC13, OC09
5	Subcontr	HEAVY DUTY ALIGMENT CENTRE	N/A	W/A
6	Labour	00215245	MULTI	ROLLER BRAKE TEST BRAKES. TWO AXLES
6	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-09-16	117238	20469646

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2619671	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	10015255	MULTI	ON ONE AXLE. INCL. SUPPORT ON STANDS, REMOVE AND FIT WHEEL, ON ONE AXLE CENTRE AXLE/REAR AXLE.
1	Labour	10005032	MULTI	BRAKE TEST ON ROLLER BRAKE TESTER. 2 OR 3 AXLE VEHICLES
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Part	2325212	Scania	BRAKE PAD
1	Part	1889543	Scania	BRAKE DISC
1	Part	2655323	Scania	LOCK NUT
1	Part	0550905	Scania	KIT PB
1	Part	0815362	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-08-01	111800	20468268

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2618927	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2024-02-01	153860	20482293

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2628333	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK
2	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2022-04-20	103539	20465469

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2617261	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	MARCOPOLO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-10-27	89412	20460783, 20460784, 20460785

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2614304	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00218733 =====
1	Labour	00215180	MULTI	SEE FORM FOR L MAINTENANCE. K DC09-DC13
1	Labour	00215185	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. ADDITIONAL WATER SEPARATING FUEL FILTER
1	Labour	00215230	MULTI	SEE THE L INSPECTION FORM. F/K/N AIR FILTER
1	Labour	00215189	MULTI	SEE MAINTENANCE FORM FOR L MAINTENANCE. K/N
1	Labour	00215048	MULTI	Scania retarder Change oil and renew filter K
1	Labour	00215080	MULTI	Brake test on roller brake tester.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	1510905	Scania	AIR FILTER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1733658	Scania	FILTER ELE
1	Part	1733658	Scania	FILTER ELE
1	Part	2562323MH	Local	WATER TRAP FILTER
1	Part	2002705	Scania	OIL FILTER
1	Part	2001228	Scania	SEALING WA
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
1	Labour	00009000	MULTI	VEHICLE HEALTH CHECK
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645

1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	1892395	Local	SCANIA GEAR OIL STO1:0 80W-90
1	Part	1771751	Local	BRAKE FLUID DOT 4
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Other	N/A	N/A	Note: Add-Blue Filter to be added additionally for F250 Vehicles.
1	Part	2544995	Scania	FILTER
1	Other	N/A	N/A	===== =====
4	Part	2734215	Scania	SAFETY CAR
5	Labour	13005117	MULTI	MEASURE ALL WHEEL ANGLES ON FRONT AXLE AND REAR AXLES USING 6X2, 6X4, 6X6

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3889544	CA379256	9BSK4X20003889 544	2021-12-14	89500	20462080

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2615074	CAPETOWN	25 Karee Road	ZA	Scania	K250

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	MARCOPOLO SA	N/A	SUBCONTRACT WORK