

WORKORDER INFORMATION

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-05-29	0	3044716
3924211	3924211	9BSG6X40003924 211	2018-06-13	6116	30350918

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1564320	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460
3614790	DURBAN	16 Imvubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Labour	05355021	MULTI	REAR SECTION WITH SHAFT AND FRONT SECTION. INCL. SUPPORT ON EG 650/652/654/660/662/664, 651/653/655/661/663/665.
1	Part	1491381	Scania	COVER
1	Part	1491382	Scania	GASKET
1	Part	PQCOU02	Local	QUICK COUPLER
1	Part	0812536	Scania	SCREW
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-06-26	0	3045366

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1564920	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-07-13	20696	30352065

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3615837	DURBAN	16 Imvubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	Safestop East Coast	N/A	FIT ORANGE DIAMOND

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-07-27	0	3045961

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1565484	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924211	2018-08-23	39808	91245691

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
23055	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168733 =====
1	Labour	00165087	MULTI	See the R inspection form. DC9 PDE. OSC 9. DC9/DC13 XPI.
1	Labour	00165010	MULTI	SEE MAINTENANCE FORM FOR R MAINTENANCE. 6X2, 6X4, 6X6, 6X2/2, 6X2/4, 6X2*4,
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	01208001	Local	RENEW ENGINE OIL CHANGE OIL FILTER CLEAN CENTRIFUGAL
1	Labour	03055021	MULTI	Excl. bleed fuel system and clear fault codes using Diagnos. DC9/DC11/D12/D16 PDE/HPI
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	=====

1	Other	N/A	N/A	Before vehicle at workshop: Predictive booking (X3/X2/X1) done? X1 Reservation /WO Quality checked? Y Parts Quality checked? Y Campaign check? Y History checked? Y VRS services offered to customer? Y Remote diagnosis performed? Y SUBC needed? N Previous offers? Y Upselling? Y Tools & equipment available? Y GOP? RAMAS GOP Credit details? RENTAL Customer contacted on X1? Yes Vehicle at workshop Vehicle at/in workshop? NIGHT SHIFT Quote done by? ALI Quote sent? Y Delay or Incident? N
1	Other	N/A	N/A	ATTEND TO CHECK AND TORQUE CHASSIS BOLTS ATTEND TO CHECK GLYCOL LEVEL (ANTI-FREEZE LEVELS)

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-08-28	39808	3046595

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1565960	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-09-26	0	3046953

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1566284	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-09-28	0	3047295

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1566622	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-10-22	0	3047625

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1566951	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-10-29	0	3047978

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1567293	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-11-05	78723	91246363

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
23693	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168735 =====
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165025	MULTI	Change oil and renew filter Scania Retarder 1
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	2562323	Scania	MAINTENANC
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771740	Local	ATF DEXRON II
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	=====

1	Other	N/A	N/A	Before vehicle at workshop: Predictive booking (X3/X2/X1) done?X1 Reservation /WO Quality checked?Y Parts Quality checked?Y Campaign check?Y History checked?Y VRS services offered to customer?Y Remote diagnosis performed?Y SUBC needed?N Previous offers?N Upselling?Y Tools & equipment available?Y GOP?RAMAS GOP Credit details?RENTAL Customer contacted on X1? Yes Vehicle at workshop Vehicle at/in workshop?Y Quote done by?Y Quote sent?Y Delay or Incident?N Extra Notes?N
1	Other	N/A	N/A	ATTEND TO CHECK AND TORQUE CHASSIS BOLTS ATTEND TO CHECK GLYCOL LEVEL (ANTI-FREEZE LEVELS)
2	Part	1485592	Scania	AIR FILTER X36
3	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-11-27	0	3048566

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1567857	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-11-28	0	3048585

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1567877	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-12-19	0	3049165

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1568452	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2018-12-20	0	3049302

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1568590	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-01-13	111095	30359235

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3621777	DURBAN	16 Imvubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	01005149	MULTI	CHECK OIL LEVEL PLUS TOP UP APPROX. 5 LITRES OF ENGINE OIL.
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-01-28	0	3049954

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1569189	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-01-29	0	3050073

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1569310	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	BREAKDOWN - SUNDAY TOP UP OIL

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-01-28	120051	91247039

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
24292	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168736 =====
1	Labour	00165117	MULTI	See the L inspection form. Incl. adjust valves. DC9/DC11/DC12/DC13 PDE
1	Labour	00165038	MULTI	Change oil and renew filter Scania Retarder 1 and 2
1	Labour	00165129	MULTI	Checking the check valve in the overflow valve. Vehicles with air suspension with extra tanks for load handl
1	Labour	00165128	MULTI	Brake test alternative 2.
1	Labour	00165048	MULTI	Check and lubricate Fifth wheel/trailer coupling.
1	Labour	00165125	MULTI	Incl. remove and fit bumper cover. Engine air filter.
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Part	2113564	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2002705	Scania	OIL FILTER
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1485592	Scania	AIR FILTER X36
1	Part	2153365	Scania	INSERT
1	Part	2145983	Scania	FLANGE SCR
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID

1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771740	Local	ATF DEXRON II
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	=====
1	Other	N/A	N/A	Before vehicle at workshop: Predictive booking (X3/X2/X1) done?X1 Reservation /WO Quality checked?Y Parts Quality checked?Y Campaign check?Y History checked?Y VRS services offered to customer?Y Remote diagnosis performed?Y SUBC needed?Y Previous offers? Upselling?Y Tools & equipment available?Y GOP?RAMAS GOP Credit details? Customer contacted on X1? Yes Vehicle at workshop Vehicle at/in workshop?Y Quote done by?Y Quote sent?Y Delay or Incident?N Extra Notes?N
1	Other	N/A	N/A	ATTEND TO CHECK AND TORQUE CHASSIS BOLTS ATTEND TO CHECK GLYCOL LEVEL (ANTI-FREEZE LEVELS)
2	Part	1759847	Scania	SAFETY ELEMENT X 24
3	Labour	19055021	MULTI	ONE MUDGUARD BRACKET (NOT THE ONE FOR THE REAR LIGHT UNIT). TRACTOR.
3	Part	2476495	Scania	MUDG BRACK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-02-26	0	3050759

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1569980	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-03-03	139260	30361026

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3623299	DURBAN	16 Imvubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
1	Labour	01005149	MULTI	CHECK OIL LEVEL PLUS TOP UP APPROX. 5 LITRES OF ENGINE OIL.
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-03-13	0	3050827

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1570032	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	BREAKDOWN - OIL TOP UP NOT COVERED IN BETWEEN SERVICES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-03-26	0	3051243

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1570446	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-03-26	0	3051300

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1570503	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-03-25	150719	10461554

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
120587	ALRODE	1 Garfield Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16205098	MULTI	L1, L2, L3, L4, L7, L8, L9, L10, L127, L128, L138, L139, L14
1	Part	1905137	Scania	BULB
2	Other	CALL01	N/A	CALL OUT FEE
2	Other	TRKM	N/A	TRAVELLING KILOMETERS
2	Labour	00008003	Local	TRAVELLING TIME
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-01	0	3051488

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1570676	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN007	N/A	RENTAL VEHICLE FINES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-06	158579	30362375

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3624319	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
1	Labour	10255095	MULTI	INCL. SUPPORT ON STANDS. GENERAL TIME FOR RENEWING PLASTIC P 1 OFF
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00005078	MULTI	FIXED SERVICE FEE (OVERTIME)
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Labour	00008003	Local	TRAVELLING TIME
1	Part	1778294	Scania	HOSE
1	Part	1422981	Scania	UNION
1	Part	1729332	Scania	HOSE CLAMP
1	Part	1896695	Local	ANTIFREEZE BULK PREMIX

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-15	160504	30362645, 30362689

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3624546	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	SHORTEN AERIAL
1	Other	SCA	N/A	SCA, LMI01-190214, Risk of Vehicles being struck by lightning. LMI01-190214
2	Other	N/A	N/A	Package 00168734 =====
2	Labour	00165091	MULTI	See form for S inspection.
2	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
2	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
2	Part	2277578	Scania	INSPECTION
2	Part	1518512	Scania	FILTER ELE
2	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
2	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
2	Other	N/A	N/A	=====
2	Other	N/A	N/A	BATTERY S/N: H9B720222 0004 + H9B720213 0005
3	Part	1485592	Scania	AIR FILTER X36

3	Other	N/A	N/A	Type: Service contract, Valid: 2018/06/01 - 2021/05/31, Code: ZA_20521_v2, Description: R&M Standard, Information: 2018/06/01-2021/05/31 RNN/18A/11930 RAMAS Payer 3 Service Intervals: 40 000kms Inclusions: *Outer Air Filter at every service *FMS Control Package
---	-------	-----	-----	--

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-19	162804	10462607

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
121637	ALRODE	1 Garfield Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16205098	MULTI	L1, L2, L3, L4, L7, L8, L9, L10, L127, L128, L138, L139, L14
1	Part	1905137	Scania	BULB
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-26	0	3052019

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1571193	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-04-30	167479	272004644

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3695	CENTURION	11 Watershed Close Louwlandia	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
2	Subcontr	NORTHCOAST TESTING GROUND	N/A	CARRY OUT COF
2	Other	N/A	N/A	CARRIED OUT COR TEST ON VEHICLE ,PASSED.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-05-27	0	3052870

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1571918	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-06-26	0	3053619

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1572619	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-06-27	0	3053798

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1572799	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-07-04	200128	91248462

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
25532	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168735 =====
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2562323	Scania	MAINTENANC
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	=====
2	Part	1485592	Scania	AIR FILTER X36
2	Other	SCA	N/A	SCA, LMI01-190214, Risk of Vehicles being struck by lightning. LMI01-190214
2	Other	N/A	N/A	ATTEND TO OUTSTANDING CAMPAIGN

2	Other	N/A	N/A	COMMUNICATIONS UNIT TESTED ONLINE YES. ALL O-KAY. LAST SEND 04-07-2019 OD 199 545KM
---	-------	-----	-----	---

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-07-23	204436	30366184

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3627612	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00165015	MULTI	SEE FORM FOR X INSPECTION
1	Other	N/A	N/A	BATTERY S/N : 00215989 - NOT VISIBLE
1	Other	N/A	N/A	===== =====
1	Other	N/A	N/A	Type: Service contract, Valid: 2018/06/01 - 2021/05/31, Code: 20521 v2, Description: R&M Standard, Information: 2018/06/01-2021/05/31 RNN/18A/11930 RAMAS Payer 3 Service Intervals: 40 000kms Inclusions: *Outer Air Filter at every service *FMS Control Package

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-07-29	0	3054676

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1573598	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-07-30	204437	11501127

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1304	Central Support Centre	106 Adcock Ingram Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	ORDER ATTACHED
1	Labour	00008000	Local	TOOK TO FILL DIESEL
1	Subcontr	RELIABLE PETROLEUM	N/A	FILL FULL DIESEL
2	Labour	16005003	MULTI	SET SPEED
6	Labour	00008000	Local	CARRIED OUT LMI
6	Other	SCA	N/A	SCA, LMI01-190214, Risk of Vehicles being struck by lightning. LMI01-190214
7	Labour	16005003	MULTI	UPDATE C300 TO VERSION 1.8
7	Other	N/A	N/A	CHECKED - CONNECTING VERSION 1.4
8	Labour	16005003	MULTI	UPDATE SOFTWARE AND CLEAR FAULT CODES USING SCANIA DIAGNOSE
9	Other	N/A	N/A	FOUND X8 REAR AXLE TYRES WORN
9	Labour	00008000	Local	CHECK BODY DAMAGES
10	Labour	16205111	MULTI	FITTING THE HEADLAMP GUARDS (GRATING) ON BOTH HEADLAMPS BUMPER, STEEL
10	Part	0EGR020	Local	HEADLIGHT GUARD
11	Labour	03205062	MULTI	RENEW 1 OR 2 BAND CLAMPS ON FUEL TANK.
11	Part	1365701	Scania	DUST COVER
12	Labour	17015074	MULTI	COVER PANEL OVER INSTRUMENT PANEL. SOFT INSTRUMENT PANEL.
12	Part	2202040	Scania	COVER

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-08-02	30	11501142

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1332	Central Support Centre	106 Adcock Ingram Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 19408006 =====
1	Labour	19008000	Local	HYDRAULIC WORK
1	Part	1771793	Local	HYDRAULIC OIL 68
1	Part	2805160	Scania	KIT HYDRAULIC
1	Other	N/A	N/A	=====
1	Part	0815363	Scania	STRAP
1	Part	0815362	Scania	STRAP
1	Part	0812389	Scania	SCREW
3	Part	1790613	Scania	POWER TAKE
3	Labour	05355028	MULTI	RETROFIT ON PREPARED VEHICLE. INCL. SUPPORT ON STANDS, REMOV EG 650/652/654/660/662/664, 651/653/655/661/663/665.
3	Part	0812541	Scania	SCREW
3	Other	N/A	N/A	FOLLOWING WORK NOT DONE, VEHICLE HAD TO LEAVE TO CUSTOMER BODY DAMAGES, SOFTWARE UPLOAD, SPEED SETTING, DIESEL FILL, KING PINS, ENGINE PROTECTION MODE AND C300
10	Labour	00008000	Local	WASH AND GO

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-08-10	207071	65316669

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
99227	EAST RAND	Cnr Sam Green & North Reef Rds	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	05015030	MULTI	INCL. REMOVE AND FIT NOISE SHIELD. GR/GRS/GRSH
1	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-08-28	0	3055478, 3055483, 3055482

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1574361	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	N/A

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-08-29	0	3055689

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1574520	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-08-30	218483	40297085, 40297106

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2072788	RICHARDS BAY	7 Brass Link Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	16205091	MULTI	ONE SIDE. HEADLAMP
1	Part	1905137	Scania	BULB
1	Other	N/A	N/A	CHECKED AND FOUND RHS HEADLIGHT BULB BLOWN. REMOVED AND FITTED NEW HEADLIGHT BULB. TESTED, FOUND OK.
2	Labour	01005149	MULTI	CHECK OIL LEVEL PLUS TOP UP APPROX. 5 LITRES OF ENGINE OIL.
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Other	N/A	N/A	CHECKED AND FOUND ENGINE OIL LEVEL LOW. TOPPED UP WITH 10 LITRES ENGINE OIL. CHECKED FOR LEAKS, NO LEAKS. TESTED, FOUND OK.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-09-18	0	3055814

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1574647	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-09-26	0	3056503

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575382	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	N/A

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-09-26	0	3056506

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575385	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-10-01	0	65317786

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
100482	EAST RAND	Cnr Sam Green & North Reef Rds	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	FAMBEZ HYDRAULICS CC	N/A	SUPPLY HYDRAULIC OIL

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	3924211	9BSG6X40003924 211	2019-10-05	240481	40297483, 40297500

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2073195	RICHARDS BAY	7 Brass Link Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168754 =====
1	Labour	00165117	MULTI	See the L inspection form. Incl. adjust valves. DC9/DC11/DC12/DC13 PDE
1	Labour	00165038	MULTI	Change oil and renew filter Scania Retarder 1 and 2
1	Labour	00165048	MULTI	Check and lubricate Fifth wheel/trailer coupling.
1	Labour	00165125	MULTI	Incl. remove and fit bumper cover. Engine air filter.
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2113564	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1485592	Scania	AIR FILTER X36
1	Part	2153365	Scania	INSERT
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	2145983	Scania	FLANGE SCR
1	Other	N/A	N/A	The product 2145983, previously replaced on 2019/01/28 at site S06, is related to work order 24292. Previous mileage 120051

1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	Add Multi groove belt if necessary.
1	Other	N/A	N/A	===== =====
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Subcontr	RICHARDS BAY VEHICLE TEST CENTRE	N/A	CARRY OUT ROLLER BRAKE TEST
3	Labour	18105069	MULTI	MANUAL WINDOW WINDER. INCL. REMOVE AND FIT ARMREST, INNER DO
3	Part	1306259	Scania	DOOR WINDO
3	Other	N/A	N/A	CHECKED AND FOUND LHS DORR WINDOW BROKEN REMOVED AND REPLACED DOOR WINDOW TESTED, FOUND OK
4	Labour	16205094	MULTI	ONE BULB
4	Part	0366010	Scania	BULB
4	Other	N/A	N/A	UPON INSPECTION, FOUND LHS STEP INDICATOR BULB BLOWN REPLACED BULB AND TESTED, FOUND OK.
5	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE
5	Other	N/A	N/A	ON INSPECTION, FOUND COOLANT CONCENTRATION LOW 15°c TOPPED UP 5 LITRES NEW COOLANT AND TESTED, FOUND OK.
6	Labour	00008000	Local	REPLACED 12 X WHEEL NUTS ON 2 X DIFF AXLES
6	Part	2285273	Scania	WHEEL NUT
6	Other	N/A	N/A	UPON SERVICING, FOUND WHEEL NUTS ON 2 X DIFF AXLES MISSING. CHECKED AND FOUND IN TOTAL 12 X WHHEL NUTS MISSING. REPLACED WHEEL NUTS AND TORQUED TO SPEC.
7	Labour	10255095	MULTI	INCL. SUPPORT ON STANDS. GENERAL TIME FOR RENEWING PLASTIC P 1 OFF
7	Part	SLCON05	Local	M12 LINE CONNECTOR
7	Other	N/A	N/A	UPON INSPECTION, FOUND AIR LEAK AT CHARGE PIPE, FOUND PIPE SHAVED THROUGH REPAIRED AIR PIPE WITH 8MM QUICK COUPLER AND TESTED, FOUND OK.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-21	0	3056656

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575505	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-15	247176	93276317

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
94087	MIDDLEBURG	12 Hektaar street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	02305014	MULTI	FIRST. INCL. DRAIN AND FILL COOLANT. 1 OFF, FIRST.
2	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
2	Labour	01005117	MULTI	TEST DRIVE VEHICLE.
2	Part	1876631	Scania	HOSE
2	Part	0816135	Scania	HOSE CLAMP
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX
2	Other	N/A	N/A	The product 1896695, previously replaced on 2019/04/06 at site S03, is related to work order 3624319. Previous mileage 158579
2	Other	N/A	N/A	ATT TO COOLANT LEAK CHECK & FOUND COOLANT HOSE PERISHED AND LEAKING. REMOVE & FIT NEW COOLANT HOSE. FILL WITH ANTIFREEZE. BLEED COOLAING SYSTEM TEST & FOUND ALL OK

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-27	0	3057028

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575882	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	N/A

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-28	0	3057078

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575936	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-29	257517	91249554

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
26511	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	03055113	MULTI	INCL. BLEED FUEL SYSTEM, TEST START AND CLEAR FAULT CODES US DC09/13 PDE
2	Part	1518512	Scania	FILTER ELE
2	Labour	03055021	MULTI	EXCL. BLEED FUEL SYSTEM AND CLEAR FAULT CODES USING DIAGNOS. DC9/DC11/D12/D16 PDE/HPI
2	Part	1873018	Scania	FUEL FILTER X 12

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-11-05	0	3057460

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1576321	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	BREAKDOWN : REPLACED FUEL FILTERS (NOT COVERED IN BETWEEN SERVICES)

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-10-08	242230	30371581

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3629940	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	CLAIM NO - 4682 DCP - 1748913F DRFR - 652375
1	Other	CALL04	N/A	CALL OUT PARTS/2ND Y WARRANTY
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	16255029	MULTI	ONE OR BOTH BATTERIES. INCL. REMOVE AND FIT BATTERY COVER AN 140/180 AH
1	Other	N/A	N/A	BATTERY S/N : NEW : 00459087 - NO SERIAL No. ON BATTERY, VIN ENGRAVED ON BATTERY OLD : 00215989 - UNREADABLE
1	Other	N/A	N/A	=====

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-11-21	273881	93277640

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
95338	MIDDLEBURG	12 Hektaar street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	05305077	MULTI	INCL. SUPPORT VEHICLE, REMOVE AND FIT NOISE SHIELD.
2	Labour	05305047	MULTI	RETARDER, REAR COOLANT PIPE. INCL. DRAIN AND FILL COOLANT, S
2	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
2	Part	1388070	Scania	RUBBER PAD
2	Part	0815123	Scania	NUT
2	Part	1876631	Scania	HOSE
2	Other	N/A	N/A	The product 1876631, previously replaced on 2019/10/15 at site S12, is related to work order 94087. Previous mileage 247176
2	Part	0816135	Scania	HOSE CLAMP
2	Other	N/A	N/A	The product 0816135, previously replaced on 2019/10/15 at site S12, is related to work order 94087. Previous mileage 247176
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX
2	Other	N/A	N/A	The product 1896695, previously replaced on 2019/04/06 at site S03, is related to work order 3624319. Previous mileage 158579, on 2019/10/15 at site S12, is related to work order 94087. Previous mileage 247176

2	Other	N/A	N/A	ATT TO COOLANT LEAK INSPECTED AND FOUND VIBRATION INSULATORS WORN CAUSING RETARDER HOSE TO SHAVE AND LEAK REMOVED AND REPLACED VIBRATION INSUALTORS WITH NUTS, COOLANT HOSE WITH CLAMPS FILLED ANTIFREEZE AND BLED SYSTEM TESTED AND FOUND IN ORDER FRAS : DRFR664916
---	-------	-----	-----	---

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-11-11	265977	91249817, 91249818

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
26619	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	00008000	Local	TAKE PLATE OUT OF SILENCER
2	Labour	00008001	N/A	ADDITIONAL FEE FOR OVER TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-11-26	0	3057900

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1576735	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-11-27	0	3058028

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1576866	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-12-16	0	3058661

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1577492	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	HL36DKGP	9BSG6X40003924 211	2019-12-20	287335	40298535, 40298539

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2074013	RICHARDS BAY	7 Brass Link Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168734 =====
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Other	N/A	N/A	The product 1771784, previously replaced on 2019/04/15 at site S03, is related to work order 3624546. Previous mileage 160504
1	Other	N/A	N/A	=====
2	Labour	00008001	N/A	ADDITIONAL FEE FOR OVER TIME
2	Part	1485592	Scania	AIR FILTER X36
2	Other	N/A	N/A	REPLACED OUTER AIR FILTER - DIRTY
6	Labour	00008000	Local	REPLACED O-RING ON TIIMING COVER
6	Part	0804870	Scania	O-RING

6	Other	N/A	N/A	UPON CARRYING OUT SERVICE, FOUND O-RING FLAT ON TIMING COVER CAUSING OIL LEAK. REPLACED O-RING AND CHECKED, FOUND OK.
7	Labour	10015208	MULTI	ON ONE AXLE. INCL. SUPPORT ON STANDS, REMOVE AND FIT SINGLE DRUM BRAKE
7	Part	1338019	Scania	O-RING PB
7	Part	0804782	Scania	RET RING PB
7	Part	1535250	Scania	LINING KIT
7	Subcontr	CASTING REPAIR SERVICES	N/A	SKIM AND RELINE
7	Other	N/A	N/A	ATTEND TO LAST AXLE BRAKES LOW. CHECKED AND FOUND LAST AXLE LININGS PAST WEAR LIMIT. REMOVED WHEELS AND DRUMS. SENT DRUMS FOR SKIMMING AND RELINING. REFIT WHEELS AND DRUMS WITH NEW LININGS, CIRCLIPS AND O-RINGS. ADJUSTED BRAKES. TEST DRIVE VEHICLE, FOUND OK.
8	Other	N/A	N/A	Package 10010010 =====
8	Labour	10015204	MULTI	Each axle
8	Labour	10017013	MULTI	Lathe both removed brake drums on one axle.
8	Labour	10015171	MULTI	Per axle, single or double wheels. Incl. support on stands, Brake linings, 4 off on 2 sides.
8	Part	1535250	Scania	LINING KIT
8	Part	1338019	Scania	O-RING PB
8	Part	0804782	Scania	RET RING PB
8	Other	N/A	N/A	==Note: This package can be used on the front or rear axles of a 4 series truck==
8	Other	N/A	N/A	=====
8	Other	N/A	N/A	ATTEND TO 2ND AXLE BRAKES LOW. CHECKED AND FOUND 2ND AXLE LININGS PAST WEAR LIMIT. REMOVED WHEELS AND DRUMS. MACHINED DRUMS AND BONDED LININGS IN HOUSE FOR 1 AXLE REFIT WHEELS AND DRUMS WITH NEW LININGS, CIRCLIPS AND O-RINGS. ADJUSTED BRAKES. TEST DRIVE VEHICLE, FOUND OK.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2019-10-21	0	3056704, 3057492

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1575553	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
---------	-----------	-------------	-----------	-------------

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-01-23	0	3059335

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1578158	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-01-27	0	3059719

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1578566	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-02-24	0	3060615

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1579441	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-13	0	3061056

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1579831	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-25	0	3061452

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1580248	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-26	0	3061512, 3061837, 3061836

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1580309	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-26	0	3061513, 3061839, 3061838

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1580310	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	REPAIR COSTS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-26	0	3061683

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1580481	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-04-22	0	3062232

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1580968	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-04-24	0	3062478

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1581208	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-24	0	3063020

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1581625	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-25	0	3063191

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1581774	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-26	0	3063336

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1581918	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-23	0	3063709

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1582287	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-24	0	3063931

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1582520	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-25	0	3063991

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1582576	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-21	0	3064397

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1582947	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-26	0	3064681

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1583242	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-27	0	3064798

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1583358	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-11	0	3065126

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1583649	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	BREAKDOWN - N3 MOOI RIVIER. CUSTOMER ADVISED TO TAKE VEHICLE TO CLOSEST WORKSHOP
1	Other	N/A	N/A	NOTE : BREAKDOWN ACCURED 29.07.2020. N3 MOOI RIVIER. DIAGNOSTICS. WORN CAB BUSHES. CALL OUT FEE: R 897.50 TRAVELING KILOMETERS: R 584.00 TRAVELING TIME: R 501 20 ADDITIONAL FEE FOR OVERTIME : R 1 670.55 TROUBLESHOOT/FAULT FINDING : R 549.93
1	Other	REN005	N/A	WHEN VEHICLE ARRIVED AT WORKSHOP. FAULT FOUND WAS TRACKROD BENT REMOVE & REPLACE
1	Other	N/A	N/A	NOTE: WHEN THE VEHICLE ARRIVED AT HARRISMITH WORKSHOP. THE TECHNICIANS WERE ABLE TO DO A PROPPER DIAGNOSTICS (HAVING ALL TOOLS ON HAND) THIS IS WHEN THEY FOUND THAT THE STEERING IS NOT CENTERED. THE TRACK ROD WAS BENT. TRACK ROD WAS REMOVED & REPLACED.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-24	0	3065392

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1583889	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-25	0	3065506

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1584010	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-26	0	3065599

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1584106	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-09-23	0	3066341

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1584816	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-09-28	0	3066661

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1585137	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-10-22	0	3066922

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1585353	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-10-25	0	3067142

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1585575	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-09	0	3067559

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1585980	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN001	N/A	EXTERNAL RENTAL / DAY

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-16	0	3067576

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1585997	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	BREAKDOWN - ATT TO BROKEN DRIVER SIDE WINDOW

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-23	0	3068108

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1586519	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-24	0	3068162

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1586564	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-12-15	0	3068542

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1586941	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-12-21	0	3069012

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1587436	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-01-26	0	3069502

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1587876	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-01-27	0	3069727

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1588093	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-02-18	0	3070118

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1588454	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-02-23	0	3070512

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1588841	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-03-25	0	3071096

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1589388	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-03-28	0	3071367, 3071496, 3071495

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1589655	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-04-21	0	3071657

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1589920	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN005	N/A	REFER TO WO 2078482

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-04-26	0	3072078

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1590318	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN003	N/A	EXCESS RENTAL / KM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-04-26	0	3072150

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1590390	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-05-25	0	3072727

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1590930	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-05-25	0	3072728

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1590931	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN008	N/A	ETOLL FOR RENTAL VEHICLES

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-05-26	0	3072793

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
1590996	IMPORTER	Cnr Nasrec Road & Harvest Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	REN004	N/A	EXTERNAL RENTAL FOR PERIOD
1	Other	REN ADMIN	N/A	RENTAL ADMIN FEE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-08	439592	50265568, 50265569

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3040311	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	05305048	MULTI	INCL. DRAIN AND FILL COOLANT, REMOVE AND FIT NOISE SHIELDS. SCANIA RETARDER
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Part	1876631	Scania	HOSE
2	Other	N/A	N/A	The product 1876631, previously replaced on 2019/10/15 at site S12, is related to work order 94087. Previous mileage 247176, on 2019/11/21 at site S12, is related to work order 95338. Previous mileage 273881
2	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE
2	Other	N/A	N/A	The product 1894323, previously replaced on 2019/10/05 at site S04, is related to work order 2073195. Previous mileage 240481

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-08-12	443644	50265602, 50265603

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3040331	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168734 =====
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	=====
2	Part	1485592	Scania	AIR FILTER X36

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-10-30	0	50266464

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3040916	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
2	Other	N/A	N/A	REMOVE WINDOW AND CLEAN OUT BROKEN GLASS
2	Other	N/A	N/A	FIT NEW WINDOW - TESTED - FOUND ALL IN ORDER
2	Labour	18105070	MULTI	ELECTRIC WINDOW WINDER. INCL. REMOVE AND FIT ARMREST, INNER
2	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
2	Part	1306260	Scania	DOOR WINDO

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-03-23	641750	50267518, 50267519

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3041875	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00165126	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Part	2782859	Scania	MAINTENANC
1	Other	N/A	N/A	Next inspection mileage: 683299
1	Other	N/A	N/A	Package 00168802 =====
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	=====
1	Part	1475431	Scania	ROTOR
1	Part	JRT12638P	Local	KIT
1	Part	2145983	Scania	FLANGE SCR
2	Part	1485592	Scania	AIR FILTER X36
3	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-14	395804	50265110

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3039997	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
2	Labour	16205091	MULTI	ONE SIDE. HEADLAMP
2	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
2	Part	1905137	Scania	BULB
2	Other	N/A	N/A	The product 1905137, previously replaced on 2019/08/30 at site S04, is related to work order 2072788. Previous mileage 218483, on 2020/05/08 at site S09, is related to work order 46740. Previous mileage 357755

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-23	402817	50265157

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3040043	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Labour	02015109	MULTI	INCL. TEST START AND LEAK TEST.
2	Part	1874363	Scania	FILLER CAP
2	Other	N/A	N/A	The product 1874363, previously replaced on 2020/03/13 at site S15, is related to work order 56445. Previous mileage 337024

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-07-21	720836	50268740, 50268741, 50268742

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3042694	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168802 =====
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	=====
1	Part	2145983	Scania	FLANGE SCR
1	Labour	00165126	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Part	1913500	Scania	FILTER
1	Part	2782859	Scania	MAINTENANC
1	Other	N/A	N/A	Next inspection mileage: 760000
2	Labour	01455037	MULTI	RENEW ENGINE AIR FILTER. HIGH AIR INTAKE
2	Part	1485592	Scania	AIR FILTER X36
3	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE

3	Other	N/A	N/A	The product 1894323, previously replaced on 2020/08/08 at site S05, is related to work order 3040311. Previous mileage 439592, on 2021/02/24 at site S16, is related to work order 7684. Previous mileage 617345
---	-------	-----	-----	--

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-09	524312	50266482, 50266483

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3040983	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
2	Other	N/A	N/A	Next inspection mileage: 560000
2	Labour	00165122	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
2	Labour	00165091	MULTI	See form for S inspection.
2	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
2	Part	2782859	Scania	MAINTENANC
2	Other	N/A	N/A	Package 00178801 =====
2	Labour	00178001	Local	CARRY OUT ADDITIONAL MAINTENANCE
2	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
2	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
2	Other	N/A	N/A	=====
2	Part	1485592	Scania	AIR FILTER X36
4	Other	N/A	N/A	FOUND INTERNAL GLOBE BLOWN - RENEW GLOBE
4	Labour	16205057	MULTI	BULB CHANGE
4	Part	0032774	Scania	BULB

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-01-04	565789	50266949

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3041335	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Next inspection mileage: 600000
1	Labour	00165038	MULTI	Change oil and renew filter Scania Retarder 1 and 2
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165125	MULTI	Incl. remove and fit bumper cover. Engine air filter.
1	Labour	00165040	MULTI	See the L inspection form. 4x4, 6x4, 6x2/4, 6x2*4
1	Labour	00165170	MULTI	Brake test on roller brake tester. Incl. check for leaks. 2-3 axles
1	Labour	00165117	MULTI	See the L inspection form. Incl. adjust valves. DC9/DC11/DC12/DC13 PDE
1	Labour	00165048	MULTI	Check and lubricate Fifth wheel/trailer coupling.
1	Part	1913500	Scania	FILTER
1	Part	2240905	Scania	FILTER
1	Part	1485592	Scania	AIR FILTER X36
1	Part	1893214	Scania	INSPECTION
1	Part	2562323	Scania	MAINTENANC
1	Part	2002705	Scania	OIL FILTER
1	Part	2002705	Scania	OIL FILTER
1	Part	0349419	Scania	O-RING
1	Part	2001228	Scania	SEALING WA
1	Other	N/A	N/A	Package 00168803 =====

1	Labour	06015035	MULTI	Between rear axles P420-520
1	Part	0153468	Scania	STRAINER X 10
1	Part	2145983	Scania	FLANGE SCR
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771751	Local	BRAKE FLUID DOT 4
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	===== =====
1	Part	2782859	Scania	MAINTENANC
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	2002705	Scania	OIL FILTER
1	Subcontr	NORTHERN CAPE TRUCK AND TRAILER ALIGNMENT CC	N/A	NC TRUCK & TRAILER

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-05-11	679119	50268020, 50268021, 50268022, 50268023

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3042240	KIMBERLEY	9 Hendrik van der Bijl Str	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00165122	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165298	MULTI	See form for S maintenance. Centrifugal oil cleaner
1	Part	2782859	Scania	MAINTENANC
1	Other	N/A	N/A	Package 00168801 =====
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	=====
2	Labour	00008000	Local	REPAIR FUEL PIPE
2	Part	SLCON05	Local	M12 LINE CONNECTOR
2	Other	N/A	N/A	Next inspection mileage: 721755
3	Part	1896695	Local	ANTIFREEZE BULK PREMIX
4	Labour	16205089	MULTI	ALL EXTERNAL LIGHTING
4	Labour	16205092	MULTI	ONE BULB. FRONT FOGLAMP/SPOTLAMP.
4	Part	0197477	Scania	BULB H1

4	Other	N/A	N/A	The product 0197477, previously replaced on 2020/09/22 at site S28, is related to work order 4413. Previous mileage 482700, on 2021/02/11 at site S28, is related to work order 5304. Previous mileage 602796
---	-------	-----	-----	---

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-20	369954	282004225, 282004226

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3653	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Other	N/A	N/A	INSPECT VEHICLE AND FOUND RHS REAR CAB AIR BELLOW LEAKING AIR
2	Other	N/A	N/A	FOUND CAB AIR BELLOW WORN - RENEW AIR BELLOW
2	Other	N/A	N/A	TESTED VEHICLE - INSPECT VEHICLE - FOUND ALL IN ORDER
2	Labour	18605104	MULTI	REAR, ONE SIDE. INCL. REMOVE AND FIT CAB BRACKET, RENEW BELL CP/CR/CG
2	Part	2477273	Scania	AIR BELLOW
2	Part	0815362	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-02-01	0	282006824

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
5231	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	TESTED ALL LIGHTS AND FOUND LHS HEADLIGHT GLOBE BLOWN - RENEW GLOBE
1	Other	N/A	N/A	TESTED - FOUND ALL IN ORDER
1	Labour	16205091	MULTI	ONE SIDE. HEADLAMP
1	Labour	16205089	MULTI	ALL EXTERNAL LIGHTING
1	Part	1905137	Scania	BULB

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-06-28	702180	282008343

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
6250	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
2	Other	N/A	N/A	INSPECT VEHICLE AND FOUND BOGIE PROPSHAFT BROKEN
2	Other	N/A	N/A	REMOVE AND RENEW PROPSHAFT WITH NECESSARY PARTS
2	Other	N/A	N/A	TESTED VEHICLE - INSPECT VEHICLE - FOUND ALL IN ORDER
2	Labour	06015035	MULTI	BETWEEN REAR AXLES P420-520
2	Part	2145983	Scania	FLANGE SCR
2	Part	2032305	Scania	PROPELLER
2	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-09-22	482700	282005450, 282005451, 282005452, 282005453

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
4413	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	MEDIUM SERV PACKAGE
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	-----
2	Labour	16205089	MULTI	ALL EXTERNAL LIGHTING
2	Labour	16205094	MULTI	ONE BULB
2	Part	0197477	Scania	BULB H1
3	Labour	05305077	MULTI	INCL. SUPPORT VEHICLE, REMOVE AND FIT NOISE SHIELD.
3	Part	1388070	Scania	RUBBER PAD
4	Labour	10005033	MULTI	IN PNEUMATIC SYSTEM
4	Labour	00008000	Local	REPAIR AIR LEAK IN CHASSIS

4	Part	PQCOU05	Local	QUICK COUPLER 12MM
4	Part	0815363	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-11-21	535955	282006173

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
4828	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008000	Local	CARRY OUT TEMP. REPAIR ON TAIL LIGHT
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Part	0815362	Scania	STRAP

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924211	2021-02-11	602796	282006961, 282006962, 282006963, 282006964, 282006965, 282006966

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
5304	PORT ELIZABETH	469 Studebaker Street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Next inspection mileage: 646135
1	Labour	00165122	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Part	2782859	Scania	MAINTENANC
1	Other	N/A	N/A	Package 00168801 =====
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Other	N/A	N/A	=====
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Part	1485592	Scania	AIR FILTER X36
2	Other	N/A	N/A	FOUND LHS SPOTLIGHT GLOBE BLOWN - RENEW GLOBE
2	Labour	16205092	MULTI	ONE BULB. FRONT FOGLAMP/SPOTLAMP.
2	Part	0197477	Scania	BULB H1

3	Other	N/A	N/A	REMOVE AND RENEW RHS REAR CAB BUMPSTOP
3	Labour	18605098	MULTI	BOTH SIDES. AT CAB TILT LOCK. CP/CR
3	Part	2470166	Scania	BUMP STOP
4	Other	N/A	N/A	FOUND O-RING PERISHED AT BLANK OFF AT FLYWHEEL HOUSING
4	Other	N/A	N/A	REMOVE AND RENEW O-RING - TESTED - FOUND ALL IN ORDER
4	Labour	00008000	Local	RENEW O-RING
4	Part	0804870	Scania	O-RING
5	Other	N/A	N/A	REMOVE AND RENEW X1 RETARDER PIPE MOUNTING
5	Labour	05305077	MULTI	INCL. SUPPORT VEHICLE, REMOVE AND FIT NOISE SHIELD.
5	Part	1388070	Scania	RUBBER PAD
6	Other	N/A	N/A	REMOVE AND RENEW INNER AIR FILTER
6	Labour	01455015	MULTI	RENEW ENGINE AIR FILTER. INCL. REMOVE AND FIT BUMPER COVER.
6	Part	1759847	Scania	SAFETY ELEMENT X 24

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-08	357755	90260480

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
46740	BLOEMFONTEIN	46 Eland Street, Quaggafontein	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	INSPECT VEHICLE LIGHTS ALL ROUND:
1	Labour	16205089	MULTI	ALL EXTERNAL LIGHTING
1	Other	N/A	N/A	REPLACE BLOWN LHS HEADLIGHT GLOBE:
1	Labour	16205091	MULTI	ONE SIDE. HEADLAMP
1	Part	1905137	Scania	BULB
1	Other	N/A	N/A	REPLACE BLOWN RHS INDICATOR GLOBE:
1	Labour	16205057	MULTI	BULB CHANGE
1	Part	1372698	Scania	BULB
1	Other	N/A	N/A	REPLACE BLOWN LHS SPOTLIGHT GLOBE:
1	Labour	16205092	MULTI	ONE BULB. FRONT FOGLAMP/SPOTLAMP.
1	Part	0197477	Scania	BULB H1

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-17	398327	907007475

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
7578	CENTRAL RETAIL	Cnr Nazrec & Alouette Rd	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Subcontr	AJR TRANSPORT	N/A	AJR UPINGTON, COOLANT LEVEL LOW
1	Other	N/A	N/A	25/06/2020 R&M FEEDBACK:Refer to job 95338 part was previously replaced. 26/06/2020 ESCALATED TO RYNO
1	Other	N/A	N/A	22/07/2020Good day Ryno Kindly assist with the above j/card. R&M rejected the claim stating: Refer to job 95338 part was previously replaced. Scania Alrode to send to Parts warranty and the response is: The pipe is shaved, shaved parts aren't claimable on warranty. Kindly assist with the j/card. Thank you,

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-18	421609	91251747, 91251748

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
28387	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
2	Labour	16205094	MULTI	ONE BULB
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Part	1372698	Scania	BULB
2	Other	N/A	N/A	The product 1372698, previously replaced on 2020/05/08 at site S09, is related to work order 46740. Previous mileage 357755
2	Part	0366010	Scania	BULB
2	Other	N/A	N/A	The product 0366010, previously replaced on 2019/10/05 at site S04, is related to work order 2073195. Previous mileage 240481

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2022-10-19	924725	91260412

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
35200	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
2	Labour	01005151	MULTI	THE FOLLOWING PROCEDURES ARE INCLUDED: START ENGINE, CONNECT SCANIA DIAGNOS
2	Labour	10505083	MULTI	INCL. SUPPORT ON STANDS, USE SCANIA DIAGNOS BEFORE AND AFTER SCANIA RETARDER 2
2	Part	2544657	Scania	PRESSURE S
2	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
2	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-09-07	760818	91256559, 91256560

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
31542	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168801 =====
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771784	Local	5TH WHEEL GREASE RENOLIT GR2 E[
1	Labour	00165122	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165298	MULTI	See form for S maintenance. Centrifugal oil cleaner
1	Part	2782859	Scania	MAINTENANC
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Other	N/A	N/A	=====
2	Part	1485592	Scania	AIR FILTER X36
3	Labour	16205123	MULTI	ONE LENS IN XENON HEADLAMP INCL. ADJUSTMENT GDLS
3	Part	2399976	Scania	LENS
3	Other	N/A	N/A	CHECK AND FOUND FRONT AND MIDDLE AXLE BRAKE LININGS BELOW SCANIA SPEC CUSTOMER WILL ATTEND TO IT HIMSELF
3	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-29	430962	91251896

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
28490	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	07015053	MULTI	ASSEMBLY. INCL. CHECK PLAY IN BALL JOINT, CHECK TOE-IN WITH
1	Part	2393679	Scania	TRACK ROD
1	Part	2082755	Scania	CASTLE NUT
1	Part	0815362	Scania	STRAP
1	Other	N/A	N/A	The product 0815362, previously replaced on 2019/08/05 at site CS1, is related to work order 1332. Previous mileage 30, on 2020/01/30 at site S12, is related to work order 97337. Previous mileage 312487, on 2020/01/30 at site S12, is related to work order 97337. Previous mileage 312487, on 2020/02/18 at site S04, is related to work order 2074607. Previous mileage 321372, on 2020/05/20 at site S28, is related to work order 3653. Previous mileage 369954, on 2020/06/26 at site S06, is related to work order 28206. Previous mileage 404615
1	Other	N/A	N/A	Package 13000001 =====
1	Labour	13005117	MULTI	Measure all wheel angles on front axle and rear axles using 6x2, 6x4, 6x6
1	Other	N/A	N/A	=====

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2022-10-11	923716	91260318

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
35115	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	01005151	MULTI	THE FOLLOWING PROCEDURES ARE INCLUDED: START ENGINE, CONNECT SCANIA DIAGNOS
1	Labour	16005015	MULTI	REFERS TO ELECTRICAL TROUBLESHOOTING, CHECKING CABLE HARNESS GENERAL
1	Labour	05355061	MULTI	SWITCH, RENEW.
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Part	1871840	Scania	VVSWITCH
1	Part	1472739	Scania	SWITCH
1	Part	0815362	Scania	STRAP
1	Other	N/A	N/A	The product 0815362, previously replaced on 2022-09-23 at site S06, is related to work order 34910. Previous mileage 923431
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-21	342922	91250751

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
27569	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	00008000	Local	FIT NEW RETATER WATER HOSE CLAMP AND REFIT EXPANSION CAP
2	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
2	Part	1896695	Local	ANTIFREEZE BULK PREMIX
2	Other	N/A	N/A	The product 1896695, previously replaced on 2019/04/06 at site S03, is related to work order 3624319. Previous mileage 158579, on 2019/10/15 at site S12, is related to work order 94087. Previous mileage 247176, on 2019/11/21 at site S12, is related to work order 95338. Previous mileage 273881, on 2020/01/30 at site S12, is related to work order 97337. Previous mileage 312487
2	Part	0816110	Scania	HOSE CLAMP

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-14	364203	91251049, 91251064

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
27836	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168734 =====
1	Labour	00165091	MULTI	See form for S inspection.
1	Labour	00165022	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Other	N/A	N/A	=====
1	Other	N/A	N/A	COMMUNICATOR C300 DATE TESTED 14-05-2020 ONLINE YES
2	Part	1485592	Scania	AIR FILTER X36
3	Labour	00008000	Local	FIT NEW O RING
3	Part	1377373	Scania	O-RING
4	Labour	18605098	MULTI	BOTH SIDES. AT CAB TILT LOCK. CP/CR
4	Part	2470166	Scania	BUMP STOP
5	Labour	00008000	Local	REMOVE AND FIT NEW ACTUATOR
5	Part	2659719	Scania	ACTUATOR

6	Labour	18705045	MULTI	RENEW 1 CAB AIR FILTER.
6	Part	1913500	Scania	FILTER
7	Labour	00008000	Local	FIT NEW NIPPLE
7	Part	0294386	Scania	LUB NIPPLE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2022-11-11	935888	91260671

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
35445	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	00008000	Local	REPAIR AIR LEAK
1	Labour	00005095	MULTI	VEHICLE HEALTH CHECK
1	Part	1898525	Scania	STRAIGHT U
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2022-09-22	923431	91260256

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
34910	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Labour	05155171	MULTI	ON GEARBOX IN TRUCK. INCL. USE VEHICLE LIFTS, CLEAN GEARBOX GR/GRS/GRSO 875R/895R/905R
1	Labour	01005151	MULTI	THE FOLLOWING PROCEDURES ARE INCLUDED: START ENGINE, CONNECT SCANIA DIAGNOS
1	Labour	00008000	Local	REMOVE AND REPLACE VALVE
1	Labour	05005136	MULTI	TEST DRIVE VEHICLE.
1	Part	0358666	Scania	PIPE COUPL
1	Part	1525270	Scania	GASKET
1	Part	1766023	Scania	GASKET
1	Part	1502384	Scania	SEAL
1	Part	1525988	Scania	NUT
1	Part	1896694	Scania	O-RING
1	Part	0394156	Scania	O-RING
1	Part	2301052	Scania	O-RING
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	0815362	Scania	STRAP
1	Part	1783288	Scania	POSITION S
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-06-26	404615	91251445, 91251446, 91251447, 91251448

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
28206	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168736 =====
1	Labour	00165117	MULTI	See the L inspection form. Incl. adjust valves. DC9/DC11/DC12/DC13 PDE
1	Labour	00165038	MULTI	Change oil and renew filter Scania Retarder 1 and 2
1	Labour	00165129	MULTI	Checking the check valve in the overflow valve. Vehicles with air suspension with extra tanks for load handl
1	Labour	00165128	MULTI	Brake test alternative 2.
1	Labour	00165048	MULTI	Check and lubricate Fifth wheel/trailer coupling.
1	Labour	00165125	MULTI	Incl. remove and fit bumper cover. Engine air filter.
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Part	2866325	Scania	MAINTENANC
1	Part	1518512	Scania	FILTER ELE
1	Part	2002705	Scania	OIL FILTER
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	0153468	Scania	STRAINER X 10
1	Part	1485592	Scania	AIR FILTER X36
1	Part	2153365	Scania	INSERT
1	Part	2145983	Scania	FLANGE SCR

1	Other	N/A	N/A	The product 2145983, previously replaced on 2019/10/05 at site S04, is related to work order 2073195. Previous mileage 240481
1	Part	WYNN357	Local	WINDSCREEN WASHER FLUID
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1892410	Local	SCANIA AXLE STO 1:0 80W-140
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	0815362	Scania	STRAP
1	Other	N/A	N/A	The product 0815362, previously replaced on 2019/08/05 at site CS1, is related to work order 1332. Previous mileage 30, on 2020/01/30 at site S12, is related to work order 97337. Previous mileage 312487, on 2020/01/30 at site S12, is related to work order 97337. Previous mileage 312487, on 2020/02/18 at site S04, is related to work order 2074607. Previous mileage 321372, on 2020/05/20 at site S28, is related to work order 3653. Previous mileage 369954
1	Other	N/A	N/A	Add Multi groove belt if necessary.
1	Other	N/A	N/A	===== =====
1	Other	N/A	N/A	COMMUNICATOR C300 ONLINE YES LAST SEND OD 404615KM
2	Labour	03205063	MULTI	T16 INCL. BLEED FUEL SYSTEM
2	Part	2568895	Scania	FUEL P-UP
3	Labour	00008000	Local	FIT O RING ON AIR CON PIPE
3	Part	1377374	Scania	O-RING
3	Other	N/A	N/A	Package 18758001 ===== =====
3	Labour	18755051	MULTI	Incl. vacuum pump, check for leaks and test function.
3	Part	1771812	Local	AIRCON GAS
3	Other	N/A	N/A	===== =====
4	Labour	01005151	MULTI	THE FOLLOWING PROCEDURES ARE INCLUDED: START ENGINE, CONNECT SCANIA DIAGNOS
4	Labour	00008000	Local	REPAIR FAULTY WIRING

5	Part	1759847	Scania	SAFETY ELEMENT X 24
---	------	---------	--------	---------------------

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-05-03	383072	91250941, 91250948

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
27734	HARRISMITH	1 Nywerheidstraat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
2	Labour	01005149	MULTI	CHECK OIL LEVEL PLUS TOP UP APPROX. 5 LITRES OF ENGINE OIL.
2	Labour	00008002	N/A	ADDITIONAL FEE FOR DOUBLE TIME
2	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
3	Labour	00008000	Local	REPAIR AIR LEAK
3	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
3	Part	PQCOU05	Local	QUICK COUPLER 12MM

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-11-02	796325	93314595

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
117628	MIDDLEBURG	12 Hektaar street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Other	N/A	N/A	N/A
1	Labour	02155023	MULTI	INCL. REMOVE AND FIT AIR PIPE AND DRAIN AND FILL COOLANT.
1	Labour	01005117	MULTI	TEST DRIVE VEHICLE.
1	Part	1745449	Scania	THERMOSTAT
1	Part	1755952	Scania	GASKET
1	Other	N/A	N/A	ATT TO OVERHEATING CHECK & FOUND THERMOSTAT STUCK IN CLOSED POSITION. REMOVE & FIT NEW THERMOSTAT TEST VEHICLE & FOUND ALL OK
1	Other	N/A	N/A	SUNDRY ITEMS

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-01-30	312487	93280732

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
97337	MIDDLEBURG	12 Hektaar street	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
2	Labour	02105116	MULTI	INCL. DRAIN AND FILL COOLANT, LIFT FRONT EDGE OF CAB USING C DC13 CP/CG/CR 14/16/19 HIGH BUMPER
2	Labour	02105053	MULTI	INCL. REMOVE AND FIT MUDGUARD HALF, BELT TENSIONER AND CUT O DC9-DC12
2	Labour	06015028	MULTI	OR REMOVE AND FIT DURING RECONDITIONING. INCL. SUPPORT THE V P602/P603/P604/P642
2	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	01005117	MULTI	TEST DRIVE VEHICLE.
2	Labour	05655069	MULTI	CARRY OUT INDIVIDUAL ADAPTATION OF OPC ACCORDING TO THE WIZA OPC
2	Part	2035612	Scania	FAN
2	Part	2447572	Scania	.POLY-V-BEL
2	Subcontr	VAN WETTENS	N/A	VAN WETTENS
2	Other	N/A	N/A	N/A
2	Labour	02305014	MULTI	FIRST. INCL. DRAIN AND FILL COOLANT. 1 OFF, FIRST.
2	Part	1930743	Scania	HOSE
2	Part	0816135	Scania	HOSE CLAMP
2	Part	1896695	Local	ANTIFREEZE PREMIX 50/50
2	Other	N/A	N/A	N/A
2	Labour	03155024	MULTI	1 HIGH PRESSURE PIPE BETWEEN INJECTOR AND ACCUMULATOR INCL. DC9/DC13 XPI
2	Part	1435361	Scania	VALVE
2	Part	1483545	Scania	TUBE

2	Part	0815362	Scania	STRAP
2	Part	1722418	Scania	CONNECTION
2	Part	0815362	Scania	STRAP
2	Other	N/A	N/A	The product 0815362, previously replaced on 2019/08/05 at site CS1, is related to work order 1332. Previous mileage 30
2	Labour	10255095	MULTI	INCL. SUPPORT ON STANDS. GENERAL TIME FOR RENEWING PLASTIC P 1 OFF
2	Part	1483545	Scania	TUBE
2	Other	N/A	N/A	N/A
2	Labour	16155059	MULTI	T27 OUTDOOR TEMPERATURE SENSOR. INCL. SUPPORT ON STANDS AND
2	Part	1100799	Scania	TEMPSENSOR
2	Other	N/A	N/A	N/A
2	Other	N/A	N/A	** ATTEND TO ABS MALFUNCTION ON DASH *** -- RHS 3rd AXLE WHEEL SPEED SENSOR PULLED OUT --
2	Labour	16805012	MULTI	1 OFF OR MORE INCL. SUPPORT IN FRAME, PLUS USE SDP3.
2	Labour	10015215	MULTI	ONE SIDE, ALSO RENEW. INCL. SUPPORT ON STANDS, REMOVE AND F

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-07-29	430772	30379972

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3637678	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
1	Labour	01005121	MULTI	TO CONFIRM REPAIR. BY E.G. STARTING OR DRIVING THE VEHICLE I
1	Other	N/A	N/A	ATTENDED TO THE BREAKDOWN AND REPORTED THAT THE TRUCK HAS TO GO TO THE WORKSHOP FOR THE REPAIR ON THE CAB BUSHES..AWAITING VEHICLE TO ARRIVE
1	Other	N/A	N/A	=====

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-01-23	309838	30374258

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
3633147	DURBAN	16 Invubu Park Place	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	01005149	MULTI	CHECK OIL LEVEL PLUS TOP UP APPROX. 5 LITRES OF ENGINE OIL.
1	Part	2405798	Local	SCANIA ENGINE OIL LDF3 10W-40 (IBC) SC3645
2	Labour	00008000	Local	ADJUST PTO VALVE.
2	Labour	01005121	MULTI	TO CONFIRM REPAIR. BY E.G. STARTING OR DRIVING THE VEHICLE I
2	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-04-15	661372	40305676

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2078482	RICHARDS BAY	7 Brass Link Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
1	Labour	00005004	MULTI	IMPLEMENT SECONDARY DIAGNOSIS.
1	Other	N/A	N/A	CUSTOMER COMPLAINT ABOUT VEHICLE BINDING. CHECKED AND FOUND THAT THE BRAKES ARE STILL IN SPEC. CHECKED THE RETARDER OIL LEVEL AND FOUND OIL LEVEL IS ON MAXIMUM. CARRIED OUT TEST FOR RETARDER AND FOUND RETARDER WORKING NORMALLY. ADJUST THE BRAKES AND CHECKED EXHAUST BRAKE AND FOUND IT WORKING. CHECKED AND FOUND THAT THE TRAILER WAS BINDING. CUSTOMER TO GET SOMEONE TO REPAIR THE TRAILER. TESTED, FOUND OK.

Chassis No.	Registration No.	VIN No.	Repair/ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-02-18	321372	40299161

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
2074607	RICHARDS BAY	7 Brass Link Road	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	N/A	N/A	Package 00168735 =====
1	Labour	00165093	MULTI	See form for M inspection.
1	Labour	00165033	MULTI	Check and lubricate Fifth wheel/trailer coupling
1	Labour	06015035	MULTI	Between rear axles P420-520
1	Labour	00165127	MULTI	Renew fuel filter. Incl. drain filter. Additional water separating fuel filter.
1	Part	2277578	Scania	INSPECTION
1	Part	1518512	Scania	FILTER ELE
1	Part	2405797	Local	SCANIA ENGINE OIL LDF3 10W-40 (210L) SC3601
1	Part	0550154	Scania	MAINTENANCE KIT RETARDER
1	Part	1771788	Local	LUBRENE LX 220EP 2 WHEEL BEARING GREASE
1	Part	1771786	Local	5TH WHEEL GREASE
1	Part	2405797	Local	SCANIA ENGINE OIL LDF3 10W-40 (210L) SC3601
1	Part	2562323	Scania	MAINTENANC
1	Other	N/A	N/A	=====
2	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Part	1759847	Scania	SAFETY ELEMENT X 24
2	Part	1485592	Scania	AIR FILTER X36
2	Other	N/A	N/A	REPLACED INNER AND OUTER AIR FILTERS - DIRTY
3	Labour	10255095	MULTI	INCL. SUPPORT ON STANDS. GENERAL TIME FOR RENEWING PLASTIC P 1 OFF

3	Part	SLCON05	Local	M12 LINE CONNECTOR
3	Part	0812913	Scania	INS.SLEEVE
3	Part	0815362	Scania	STRAP
3	Other	N/A	N/A	ATTENDED TO AIR LEAK. CHECKED AND FOUND AIR LEAK ON 12MM AIR PIPE IN CHASSIS. REMOVED AIR PIPE, REAPIRED WITH 12MM STEEL LINE CONNECTORS AND REFIT AND SECURED TESTED, FOUND NO AIR LEAKS.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-20	341934	202068269

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
56574	ROSSLYN	79 Willem Cruywagen	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
1	Labour	00008000	Local	AJUST AIR CONTROL VALVE

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-03-13	337024	202068234

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
56445	ROSSLYN	79 Willem Cruywagen	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
1	Part	1874363	Scania	FILLER CAP
1	Labour	02015109	MULTI	INCL. TEST START AND LEAK TEST.

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2020-12-18	562498	302008936, 302008937

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
7544	BEAUFORT WEST	Fabriek Straat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008001	Local	ADDITIONAL FEE FOR OVER TIME
2	Labour	16255026	MULTI	2 OFF, WITH HYDROMETER. INCL. REMOVE AND FIT BATTERY COVER.
2	Labour	16255029	MULTI	ONE OR BOTH BATTERIES. INCL. REMOVE AND FIT BATTERY COVER AN 140/180 AH
2	Part	2133962V	Local	VARTA BATTERY M18

Chassis No.	Registration No.	VIN No.	Repair/ ArrivalDate	Mileage (KM)	Invoice No.
3924211	NN70923	9BSG6X40003924 211	2021-02-24	617345	302009082, 302009083

Workorder No.	Workshop Name	Address	Country	Brand	Chassis Model
7684	BEAUFORT WEST	Fabriek Straat	ZA	Scania	G460

Job No.	Line Type	Part/Labour	Item Type	Description
1	Other	CALL01	N/A	CALL OUT FEE
1	Other	TRKM	N/A	TRAVELLING KILOMETERS
1	Labour	00008003	Local	TRAVELLING TIME
1	Labour	00008002	Local	ADDITIONAL FEE FOR DOUBLE TIME
2	Labour	02305014	MULTI	FIRST. INCL. DRAIN AND FILL COOLANT. 1 OFF, FIRST.
2	Labour	02005015	MULTI	USING COOLING SYSTEM TESTER 587048
2	Part	2038638	Scania	HOSE
2	Part	0815363	Scania	STRAP
2	Part	1894323	Scania	ANTIFREEZE 5LT CONCENTRATE